

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 7:36 am, Apr 19, 2016

Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company : <b>LIME ROCK RESOURCES II-A, LP</b>	Contact : <b>Mike Barrett</b>	
Address : <b>1111 Bagby Street Suite 4600, Houston, TX 77002</b>	Telephone No. : <b>575-365-9724</b>	
Facility Name : <b>North Vacuum Abo North Unit #82 (NVANU #82)</b>	Facility Type: <b>Battery</b>	
Surface Owner : <b>State</b>	Mineral Owner:	Lease No. <b>30-025-32693</b>

### LOCATION OF RELEASE

Unit Letter <b>P</b>	Section <b>2</b>	Township <b>17S</b>	Range <b>34E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Eddy</b>
-------------------------	---------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	--------------------

Latitude **32.857914 N** Longitude **-103.5242233 W**

### NATURE OF RELEASE



Type of Release : <b>Unknown</b>	Volume of Release : <b>Unknown</b>	Volume Recovered: <b>Unknown</b>
Source of Release : <b>Unknown</b>	Date and Hour of Occurrence: <b>Unknown</b>	Date and Hour of Discovery:
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? <b>Amber Groves</b>	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* **Amber Groves with the NM State Land Office and the NMOCD required the impacted areas around the old tank battery be delineated to determine the extent of the vertical contamination.**

Describe Area Affected and Cleanup Action Taken.\* **Lime Rock Resources contacted Talon/LPE to perform initial site assessment and sampling activities in order to generate a work plan.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: <b>Michael Barrett</b>	Approved by District Supervisor: 		
Title: <b>Production Superintendent</b>	Approval Date: <b>04/19/2016</b>	Expiration Date: <b>06/19/2016</b>	
E-mail Address: <b>mbarrett@limerockresources.com</b>	Conditions of Approval: <b>Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure SLO concurrence/approval.</b>		Attached <input type="checkbox"/> <b>1RP 4252</b>
Date: <b>4/18/2016</b>	Phone: <b>575-365-9724</b>		

\* Attach Additional Sheets If Necessary

nJXK1611027253  
pJXK1611027315