District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexic

Energy Minerals and Natural I By JKeyes at 8:13 am, Apr 25, 2016

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

						OPERA'	ГOR	☐ Initi	al Report Final R	enort	
Name of Company Fulfer Oil + Catile						Contact Gara Wink					
Address P.D. Box 1227 Jal NM 88252						Telephone No. 575-350-5095					
Facility Name South Langue Tal Mait Enjection Facility Type Water Injection Station											
Surface Owner 6129 Fulfer Mineral Owner						API No.					
LOCATION OF RELEASE											
TT 1. T						South Line	Feet from the	East/West Line	County		
I 7 255 37E 1650' 50						uth	960'	Fast	Lea		
Latitude Longitude											
NATURE OF RELEASE											
Type of Release froducto Volume of Release 150 Volume Recovered 5											
Source of Release 500 bbl Flo Tank Struck by Lightning.											
Was Immediate Notice Given? Yes □ No □ Not Required						If YES, To Whom?					
By Whom? Gary W. Wink						Missing Warrender					
Was a Watercourse Reached?						Date and Hour \$-22-15 10:13 A.W. If YES, Volume Impacting the Watercourse.					
☐ Yes ☐ No						11/4					
If a Watercourse was Impacted, Describe Fully.*											
Describe Cause of Problem and Remedial Action Taken * / 1 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2											
in wells. Backhoe was exal I highthing struck 500 bbi &6 reduced nater tank, Shut											
Describe Cause of Problem and Remedial Action Taken. * Lighthing struck 500 bbl F6 Produced nater tank. Shut in wells. Backhoe was sent out to location. Backhoe dus ont contaminated area and hauled off.											
Describe Area Affected and Cleanup Action Taken.* 300' VIGO' Inside he Hen 50' VSO' and side he Il											
Describe Area Affected and Cleanup Action Taken.* 300' x 100' Inside battery. 50' x 50' outside hattery. Ous out affected orca to 1'-2' and hauled off. Sampler were taken to lab & came back											
clean We were given permission to backfill. 144 yds were hauted out and 156 yds were hauted in											
I licieby certif	y mat me ir	normation giv	ven above	is true and comp	ete to the	best of my	knowledge and in	derstand that nure	ant to NMOCD rules and	7,0	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The constitution of the constit											
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the chivilon	ment. In ac	dition, NIVIO	CD accept	tance of a C-141	eport do	es not relieve	the operator of r	esponsibility for co	empliance with any other	"	
federal, state,	or local law	s and/or regu	lations.			-	OII CONG	EDILLETON	DIMIGNOST		
Signature: Lay W. Wink						OIL CONSERVATION DIVISION					
						Jan X lhyer					
Printed Name: Gary W. Wink						Approved by Environmental Specialist:					
Title: Production Foreman						pproval Date	04/25/2016	Expiration I	Expiration Date:		
E-mail Addres	s: Garyu	sinted/	eaener	gy - Com	C	onditions of Approval:					
ate: 4-18-16 Phone: 575-390-509											
.tach Additi	onal Sheet	s If Necessa	rv		4-419						