

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 8:19 am, Apr 29, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	EOG Resources, Inc.	Contact	Zane Kurtz
Address	5509 Champions Drive, Midland, TX 79706	Telephone No.	432-425-2023
Facility Name	Rattlesnake 28 Fed Com 703H	Facility Type	CTB - Lay Flat Water Transfer Line

Surface Owner	BLM	Mineral Owner	BLM	API No.	30-0254-2875
---------------	-----	---------------	-----	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section 28	Township 26S	Range 33E	Feet from the 230'	North/South Line S	Feet from the 1766'	East/West Line E	County Lea
-------------	---------------	-----------------	--------------	-----------------------	-----------------------	------------------------	---------------------	---------------

Latitude 32.0160 Longitude -103.5844

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	230	Volume Recovered	15
Source of Release	Lay Flat Water Line	Date and Hour of Occurrence	April 28, 2016	Date and Hour of Discovery	0900
Was Immediate Notice Given?	If YES, To Whom? Shelly Tucker, BLM				
	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required				
By Whom?	Zane Kurtz	Date and Hour	April 28, 2016 @ 1300		
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.				
	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				



If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*

We had 2 releases from a lay flat water line moving produced water from a CTB to a drill rig. Both releases were from connection failures. First release was 200bbls with no recovery in a dry creek bed and ran 1/8 mile. Second release was 1/2 mile down line and released 30 bbls and was able to recover 15 bbls. Consultant will delineate the spill area and prepare work plan to address the impacted areas. 2nd release is located at 32.0163, -103.5952.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Zane Kurtz		Approved by Environmental Specialist: 	
Title: Sr. Environmental Rep., EOG Resources, Inc.		Approval Date: 04/29/2016	Expiration Date: 06/29/2016
E-mail Address: zane_kurtz@eogresources.com		Conditions of Approval:	
Date: April 28, 2016 Phone: 432-425-2023		Discrete samples only. Delineate and remediate per NMOCOD guidelines. Ensure BLM concurrence/approval.	
		Attached <input type="checkbox"/> IRP 4265	

* Attach Additional Sheets If Necessary

nJXK1612029745
pJXK1612029884