

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 7:36 am, May 16, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Key Energy Services, LLC	Contact Bobby Sisson	
Address 1301 McKinney Street, Suite 1800, Houston, TX 77010	Telephone No. 806-401-4349	
Facility Name Atha SWD	Facility Type SWD	
Surface Owner Dasco & McCasland	Mineral Owner Dasco & McCasland	API No. 30-025-04861



LOCATION OF RELEASE

Unit Letter M	Section 31	Township 21S	Range 36E	Feet from the 660'	North/South Line South Line	Feet from the 660'	East/West Line West Line	County Lea
---------------	------------	--------------	-----------	--------------------	-----------------------------	--------------------	--------------------------	------------

Latitude 32° 42' 99.3" N Longitude 103° 31' 03.9" W

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5 bbl.	Volume Recovered 5 bbl.
Source of Release Fiberglass flowline	Date and Hour of Occurrence 04/26/2016 08:50 am	Date and Hour of Discovery 04/26/2016 08:50 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. n/a	
If a Watercourse was Impacted, Describe Fully.* Not applicable.		
Describe Cause of Problem and Remedial Action Taken.* A leak coming from a fiberglass flowline caused by soil settling spilled onto the location.		
Describe Area Affected and Cleanup Action Taken.* Standing fluids were immediately picked up using a vacuum truck. Fiberglass flowline has been repaired. No further action required		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Bobby Sisson		Approved by Environmental Specialist: 	
Title: Area Director		Approval Date: 05/16/2016	Expiration Date: 07/16/2016
E-mail Address: bsisson@keyenergy.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> 1RP 4279
Date: 04/27/2016	Phone: 806-401-4349		

* Attach Additional Sheets If Necessary

nJXK1613727210
pJXK1613727347