

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 1:29 pm, May 18, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	MAGNUM PRONTO 32 STATE SWD #001	Facility Type:	Tank Battery

Surface Owner:	State	Mineral Owner:	API No.	30-025-41354
----------------	-------	----------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	32	19S	32E	2470	South	2120	West	Lea

Latitude 32.6163979

Longitude 103.7900543

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 650bbls of produced water	Volume Recovered: 647bbls of produced water
Source of Release: Fiberglass Flange	Date and Hour of Occurrence: 5/8/2016 9:00 am	Date and Hour of Discovery: 5/8/2016 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Keyes- NMOCD / Ms. Groves - SLO	
By Whom? Robert Grubbs Jr.	Date and Hour: 05-08-2016 3:13pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A fiberglass flange failed due to high pressure.

Describe Area Affected and Cleanup Action Taken.*

The release was contained within a Falcon lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. The containment will be cleaned and the facility will be put back into operation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: 		
Title: Senior Environmental Coordinator	Approval Date: 05/18/2016	Expiration Date: 07/18/2016	
E-mail Address: rgrubbs@concho.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> 1RP 4286
Date: 05-18-2016	Phone: 432-683-7443		

* Attach Additional Sheets If Necessary

nJXK1613948420
pJXK1613948529