

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 2:49 pm, Jun 01, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Fasken Oil and Ranch, Ltd	Contact Aaron Pachlhofer
Address 6101 Holiday Hill Road	Telephone No. 432-687-1777
Facility Name Cabot "Q" SWD No. 1	Facility Type SWD

Surface Owner Barbie Beer	Mineral Owner State	API No. 30-025-022690
---------------------------	---------------------	-----------------------

LOCATION OF RELEASE

Unit Letter L	Section 7	Township 15S	Range 35E	Feet from the 1980	North/South Line South	Feet from the 560	East/West Line West	County Lea
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 33.029897° Longitude -103.454002°

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 110 BBLs	Volume Recovered 100 BBLs
Source of Release Injection Line	Date and Hour of Occurrence 5/28/16 8:00 a.m.	Date and Hour of Discovery 5/28/16 10:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Called to NMOCD Emergency line phone line	
By Whom? Aaron Pachlhofer	Date and Hour 5/28/16 7:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Injection line failed near wellhead. Check valve to well head failed and allowed water to flow to surface. All wells shut in. Line repaired on 5/31/16 and service returned..

Describe Area Affected and Cleanup Action Taken.*

The well pad, interior of the firewall, leases road, and a about 5,000 square feet of pasture were affected by the release. All fluids were removed. Further cleanup is pending scheduling.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Aaron Pachlhofer		Approved by Environmental Specialist: 	
Title: Environmental Coordinator		Approval Date: 06/01/2016	Expiration Date: 08/01/2016
E-mail Address: aaron[<u>for</u>]@forl.com		Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.	
Date: 6/1/16 Phone: 432-687-1777		Attached <input type="checkbox"/> IRP 4298	

* Attach Additional Sheets If Necessary

nJXK1615353185
pJXK1615353302