

RECEIVED**By JKeyes at 9:46 am, Jun 08, 2016**

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**☒ Initial Report ☐ Final Report



Name of Company	LEGACY RESERVES OPERATING LP	Contact	Daniel Rosa
Address	PO BOX 10848, MIDLAND, TX 79702	Telephone No.	432-631-0099
Facility Name	Rock Queen Sand Unit # 50	Facility Type	Injection Well
Surface Owner	Mineral Owner	API No. 30-005-00882	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	26	13 S	31 E	660'	South	990'	East	Chaves

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	15 bbls	Volume Recovered	5 bbls
Source of Release	1/2' Bleeder Valve	Date and Hour of Occurrence	Date and Hour of Discovery		
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Maxi Brown - Left message on the phone with call back number.		
By Whom?	Daniel Rosa	Date and Hour	6/7/2016 @ 11:03 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
N/A					
Describe Cause of Problem and Remedial Action Taken.*					
Cow rubbed up against valve causing release. Vacuum truck called out to pick up free standing water. Clean up with backhoe.					
Describe Area Affected and Cleanup Action Taken.*					
100' x 25' south of wellhead to the edge of location. Vacuum truck called out to pick up free standing water. Clean up with backhoe. Pickup damp top soil and haul off. Fill in with clean dirt with NMOCD approval.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Daniel Rosa		Approved by Environmental Specialist: 			
Title: Production Foreman		Approval Date: 06/08/2016		Expiration Date: 08/08/2016	
E-mail Address: Drosa@legacyLP.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 6/7/2016		Discrete samples only. Delineate and remediate per NMOCD guidelines.		1RP 4303	
Phone: 432-631-0099					

* Attach Additional Sheets If Necessary

nJXK1616035049
pJXK1616035141**Scanned by CamScanner**