

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 10:56 am, Jun 13, 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: RED BULL 35 FEDERAL #001H	Facility Type: Well	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-34015

LOCATION OF RELEASE

Unit Letter K	Section 35	Township 25S	Range 33E	Feet from the 1980'	North/South Line South	Feet from the 1980'	East/West Line West	County Eddy Lea
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	-------------------------------

Latitude 32.0851822 Longitude -103.5452042

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 5 bbls Oil ; 10 bbls PW	Volume Recovered: 4 bbls Oil ; 8 bbls PW
Source of Release: Stuffing Box	Date and Hour of Occurrence: 6/3/2016 unknown	Date and Hour of Discovery: 6/3/2016 11:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a stuffing box leak. Vacuum trucks were dispatched to recover standing fluid and the pad area was scraped to pick up impacted material. The material was disposed of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.*

This release remained on the pad area at the wellhead. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amanda T. Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: <i>Jamie Keyes</i>	
Title: Senior Environmental Coordinator	Approval Date: 06/13/2016	Expiration Date: 08/13/2016
E-mail Address: atrujillo@concho.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM	Attached <input type="checkbox"/> 1RP 4309
Date: June 10, 2016 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

concurrency/approval.

nJXK1616539232
pJXK1616539316