

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 1:06 pm, Jun 13, 2016

Form C-141

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jose A Zepeda	
Address: 29 Vacuum Complex Lane	Telephone No. 575-391-3165	
Facility Name: ABO 4	Facility Type: Trunk Line	
Surface Owner: State	Mineral Owner: N/A	API No. 30-025-08526

LOCATION OF RELEASE

Unit Letter I	Section 27	Township 17S	Range 35E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Produce Water	Volume of Release: 38	Volume Recovered: 25
Source of Release: Flow Line	Date and Hour of Occurrence 06/11/2016 1350	Date and Hour of Discovery SAME
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes	
By Whom? Jose A Zepeda	Date and Hour: 06/13/16 0945 via email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

On June 11, 2016 at 1350 MDT at ABO 4 a leak was found on a Trunk line below ground level on south side of CR50, resulting in a release of 38 bbls of Produce Water with 25 bbls recovered. Immediate action was to shut in all manual header valves. Spill site will be remediated according to COPC and NMOCD guidelines.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: JOSE A ZEPEDA		OIL CONSERVATION DIVISION	
Printed Name: Jose A Zepeda		Approved by Environmental Specialist: <i>Jamie Keyes</i>	
Title: LEAD HSE		Approval Date: 06/13/2016	Expiration Date: 08/13/2016
E-mail Address: Jose. A. Zepeda@conocophillips.com		Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.	
Date: 06/13/2016 Phone: 575-391-3165		Attached <input type="checkbox"/> 1RP 4310 nJXK1616547061 pJXK1616547134	

* Attach Additional Sheets If Necessary