

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 7:22 am, Jun 21, 2016

Form C-141
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: DECKARD FEDERAL COM #002H	Facility Type: Battery	
Surface Owner: Fee	Mineral Owner: Federal	API No. 30-025-41382

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	13	24S	33E	190'	North	1980'	West	Lea

Latitude 32.2243538 Longitude -103.5281677

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 12 bbls Oil	Volume Recovered: 10 bbls Oil
Source of Release: Flare	Date and Hour of Occurrence: 6/11/2016 unknown	Date and Hour of Discovery: 6/11/2016 9:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused when the motor valve on tester stayed stuck open causing a drop in pressure. Motor valve for water side did not open as well filling up knockout and sending it to flare. A vacuum truck was dispatched to recover all standing fluid and Microblaze was applied to the pasture.

Describe Area Affected and Cleanup Action Taken.*

This spill impacted the containment around the flare and the nearby pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amanda T. Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: <i>Jani Keyes</i>	
Title: Senior Environmental Coordinator	Approval Date: 06/21/2016	Expiration Date: 08/21/2016
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 20, 2016 Phone: 575-748-6940	Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/ approval.	IRP 4315

* Attach Additional Sheets If Necessary

nJXK1617326344
pJXK1617326446