

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 10:16 am, Jul 19, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Jose A Zepeda	
Address: 29 Vacuum Complex Lane	Telephone No. 575-391-3165	
Facility Name: MCA CO2 Compressor	Facility Type: Vent Line	
Surface Owner: BLM	Mineral Owner: N/A	API No. 30-025-00608 Closest Well

LOCATION OF RELEASE

Unit Letter M	Section 21	Township 17S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy Lea
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	--------------------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 45	Volume Recovered: 40
Source of Release: Vent Line	Date and Hour of Occurrence 07/18/2016 1000	Date and Hour of Discovery SAME
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes	
By Whom? Jose A Zepeda	Date and Hour: 07/19/16 0930 via email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken. *


On July 18, 2016 at 1000 MDT at MCA CO2 Compressor a leak was found on a vent line resulting in a release of 45 bbls of Oil with 40 bbls recovered. Immediate action was to shut in line and work order submitted for repairs. Spill site will be remediated according to COPC and NMOCD guidelines.

Describe Area Affected and Cleanup Action Taken. *

Pasture area 20' X 20' X 8" deep.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: JOSE A ZEPEDA	Approved by Environmental Specialist: 	
Printed Name: Jose A Zepeda		
Title: LEAD HSE	Approval Date: 07/19/2016	Expiration Date: 09/19/2016
E-mail Address: Jose. A. Zepeda@conocophillips.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/ approval.	Attached <input type="checkbox"/> IRP 4354
Date: 07/19/2016	Phone: 575-391-3165	nJXK1620136648 pJXK1620136955

* Attach Additional Sheets If Necessary