

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 1:23 pm, Jul 20, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	EOG Resources, Inc.	Contact	Zane Kurtz
Address	5509 Champions Drive, Midland, TX 79706	Telephone No.	432-425-2023
Facility Name	Diamond 8 Fed Com #1	Facility Type	Oil Well and Tank Battery
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-025-30632

LOCATION OF RELEASE



Unit Letter	Section 8	Township 25S	Range 34E	Feet from the 660'	North/South Line N	Feet from the 2310'	East/West Line E	County Lea
-------------	--------------	-----------------	--------------	-----------------------	-----------------------	------------------------	---------------------	---------------

Latitude 31.6908 Longitude -102.8210

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	130bbls	Volume Recovered	80bbls
Source of Release	Fire melted poly lines	Date and Hour of Occurrence	7-19-2016	Date and Hour of Discovery	1200
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NA			
By Whom?	NA	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.* NA					
Describe Cause of Problem and Remedial Action Taken.* Fluid was sent to flare scrubber and out the flare. Caused fire out the flare landed on ground and burned poly lines and released produced water. Vac truck removed all standing fluid. Consultant will delineate the vertical and horizontal depths of the release and submit a work plan for cleanup. Cleanup method will be based on test results to see if dig and haul is necessary.					
Describe Area Affected and Cleanup Action Taken.*					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	Zane Kurtz		
Title:	Sr. Environmental Rep., EOG Resources, Inc.		
E-mail Address:	zane_kurtz@eogresources.com		
Date:	7-20-2016	Phone:	432-425-2023
OIL CONSERVATION DIVISION		Approved by Environmental Specialist: 	
Approval Date:		07/20/2016	Expiration Date: 09/20/2016
Conditions of Approval:		Attached <input type="checkbox"/>	
Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/approval.		IRP 4356 nJXK1620248051 pJXK1620248133	

* Attach Additional Sheets If Necessary