

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 3:14 pm, Aug 02, 2016

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report


Name of Company: Sheridan Production Company, LLC	Contact: Ed Hamblin	
Address:	Telephone No.: 432.813.4831	
Facility Name: Coogan Federal Battery #1 & #3	Facility Type: Oil Storage Battery	
Surface Owner: To Be Provided On Final	Mineral Owner: To Be Provided On Final	API No.: NMLC-0655525

LOCATION OF RELEASE

Unit Letter NE SW	Section 1	Township 21S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
----------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.5140915 Longitude -103.1173477

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 20 BBL	Volume Recovered: 15 BBL
Source of Release: Oil Storage Tank	Date and Hour of Occurrence: 7/27/2016 8:15 AM	Date and Hour of Discovery: 7/27/2016 8:15 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos (BLM)	
By Whom? Ed Hamblin	Date and Hour 7/28/2016 4:44 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Oil storage tank developed a hole in the bottom along the seam. A vacuum truck was mobilized upon discovery and recovered freestanding fluid.		
Describe Area Affected and Cleanup Action Taken.* The area affected was contained inside of the berm. Vertical & horizontal delineation will be determined and a cleanup plan of action will be prepared.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Ed Hamblin	Approved by Environmental Specialist: 	
Title: EHS Coordinator	Approval Date: 08/02/2016	Expiration Date: 10/02/2016
E-mail Address: ed.hamblin@sheridanproduction.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> IRP 4385
Date: 8/1/2016	Phone: 432.813.4831	

* Attach Additional Sheets If Necessary

nJXK1621554732
pJXK1621554788