State of New Mexic Energy Minerals and Natural

> **Oil Conservation Division** 1220 South St. Francis Dr.

Submit I Copy to appropriate District Office in accordance with 19 15.29 NMAC.

1220 0, 50, 1100	15 D1. Duik	110,1000	·	Sa	inta Fe	e, NM 875	05				
			Rele	ase Notific	atio	n and Co	orrective A	ction			
					OPERATOR		🛛 Initia	l Report [Final Re	port	
Name of Company: COG Operating LLC							Contact: Ro				
						Felephone No. 432-685-4304					
Facility Name: KING COBRA 2 STATE #001H						Facility Type: Flare					
Surface Owner: State Mineral Owner)wner:	API No. 30-025-40388						
LOCATION OF RELEASE											
Unit Letter	Letter Section Township Range Feet from the Nor		North	South Line Feet from the East/		East/West Line					
A	2	195	_34E	460		North	460	East		Lea	
				Latitude 32.6	695774	1 Longitude	e -103.5239563				
NATURE OF RELEASE											
Type of Release:						Volume of		Volume Recovered:			
	725	Oil					6bbls Oil		05bbls Oil		
Source of Release:							our of Occurrenc	e: Date and I	Date and Hour of Discovery: 7/26/2016 6:00 pm		
Flare Was Immediate Notice Given?							7/26/2016 6:00 pm 7/26/2016 6:00 pm If YES, To Whom?				
Yes No Not Required											
By Whom?							Date and Hour:				
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.				
🗌 Yes 🛛 No											
If a Watercou	rse was Im	pacted, Descri	bc Fully.*			1					
			-								
Describe Caus	e of Proble	m and Rame	lial Action	Taken *							
Describe Cau	SC 01 1 100M	an and Kenici	nai Actioi	i Taken.							
Г	his release	was caused b	y oil dum	valve that failed	causing	g the fluid to g	go to the flare. Re	placed the dump va	lve on the FW	KO.	
Describe Area	A 60-11-1			*							
Describe Area	i Affected a	ind Cleanup P	iction Tak	en."							
A 28'X26'in								l to delineate any po any significant ren			ie
								I understand that pu			

regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	Robert Arch	OIL CONSER	VATION I	DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist:			
_Title:	Senior Environmental Coordinator	Approval Date: 08/02/2016	Expiration D	Expiration Date: 10/02/2016	
E-mail Address:	rgrubbs@concho.com	Conditions of Approval:		Attached	
Date: August 1, 20		Discrete samples only. Delineate and NMOCD guidelines.	remediate per	1RP 4386	
* Attach Additional	Sheets If Necessary	0		nIXK1621555223	

By JKeyes at 3:22 pm, Aug 02, 2016

RECEIVED