

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

Form C-141  
Revised August 8, 2011

By JKeys at 8:53 am, Aug 17, 2016

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <b>ConocoPhillips</b>	Contact: <b>Jose A Zepeda</b>	
Address: <b>1410 N West County Road</b>	Telephone No. <b>575-391-3165</b>	
Facility Name: <b>SEMU BTB #156</b>	Facility Type: <b>Flowline</b>	
Surface Owner: State	Mineral Owner: N/A	API No. 30-025-35537

### LOCATION OF RELEASE

Unit Letter	Section 25	Township 20S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Lea</b>
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release: <b>Produce Water</b>	Volume of Release: <b>5.29</b>	Volume Recovered: 0
Source of Release: <b>Flowline</b>	Date and Hour of Occurrence <b>08/15/2016 1100</b>	Date and Hour of Discovery <b>SAME</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes	
By Whom? <b>Jose A Zepeda</b>	Date and Hour: <b>08/16/16 0700 via email</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken. \*


ENV – Agency Reportable – MCBU – Permian – 5.29 bbls of Produce Water – SEMU BTB #156 – Hobbs – RR2 – On August 15, 2016 at 1100 MDT at SEMU BTB #156 a leak was found on a flowline resulting in a release of 5.29 bbls of Produce Water with 0 bbls recovered. Immediate action was to shut in well, turned in work order for repairs. Spill site will be remediated according to COPC and NMOCD guidelines.

Describe Area Affected and Cleanup Action Taken. \*

Pasture area 20' X 20' X 8" deep.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: <b>JOSE A ZEPEDA</b>	Approved by Environmental Specialist: 	
Printed Name: Jose A Zepeda		
Title: LEAD HSE	Approval Date: <b>08/17/2016</b>	Expiration Date: <b>10/17/2016</b>
E-mail Address: <b>Jose. A. Zepeda@conocophillips.com</b>	Conditions of Approval: <b>Discrete samples only. Delineate and remediate per NMOCD guidelines.</b>	Attached <input type="checkbox"/> <b>IRP 4402</b>
Date: 08/16/2016	Phone: 575-391-3165	

\* Attach Additional Sheets If Necessary

nJXK1623031839  
pJXK1623031915