

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 7:43 am, Aug 31, 2016

Form C-141
Revised August 8, 2011

in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Apache Corporation	Contact Bruce Baker
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name NEDU North Injection Line (Near the NEDU 391)	Facility Type: Flowline

Surface Owner State	Mineral Owner	API No. 30-025-06376
---------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter L	Section 2	Township 21S	Range 37E	Feet from the 2310	North/South Line FSL	Feet from the 988	East/West Line FWL	County Lea
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	---------------

Latitude N32.507 Longitude W103.1391602

NATURE OF RELEASE

Type of Release: produced water	Volume of Release 20 barrels of produced water	Volume Recovered 15 barrels of produced water
Source of Release: Steel buried flow line	Date and Hour of Occurrence 8/24/2016	Date and Hour of Discovery 8/24/2016 at 4:30 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes (NMOCD)	
By Whom? Bruce Baker	Date and Hour 8/25/2016 at 2:11 p.m. via email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A release occurred due to a dime size hole developed in the 6X2 inch welded reducer. The master valve was closed to isolate the line and a vacuum truck was dispatched to pick-up standing fluid. The line was repaired.

Describe Area Affected and Cleanup Action Taken.* The release was approximately 100 feet east of the NEDU 371 lease pad and affected approximately 1600 square feet of ROW and pasture. The site was mapped and initial samples were collected and sent to commercial laboratory for analysis.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Bruce Baker		Approved by Environmental Specialist: <i>Jamie Keyes</i>	
Title: Environmental Technician		Approval Date: 08/31/2016	Expiration Date: 10/31/2016
E-mail Address: larry.baker@apachecorp.com		Conditions of Approval:	
Date: 8/30/2016 Phone: (432) 631-6982		Discrete samples only. Delineate and remediate per NMOCD guidelines.	
		Attached <input type="checkbox"/> IRP 4426 njXXK1624427625 pjXXK1624427702	