

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 12:33 pm, Sep 07, 2016

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: ConocoPhillips	Contact: Joseph McLaughlin	
Address: 3695 Highway 285, Orla TX	Telephone No. 806-567-2790	
Facility Name: Buck Federal CTB	Facility Type: Central Tank Battery	
Surface Owner: NMOCD	Mineral Owner: NMOCD	API No.

LOCATION OF RELEASE

Unit Letter P	Section 17	Township 26S	Range 32E	Feet from the North	North/South Line North	Feet from the West	East/West Line West	County LEA
-------------------------	----------------------	------------------------	---------------------	-------------------------------	----------------------------------	------------------------------	-------------------------------	----------------------

Latitude **N32°2'14"** Longitude **W103°41'48"**

NATURE OF RELEASE

Type of Release: Produced Water Spill	Volume of Release: 240 BBLS	Volume Recovered: 235 BBLS
Source of Release: Produced Water tank over flow (see Lat/Long above).	Date and Hour of Occurrence 09/5/2016 10:00 pm	Date and Hour of Discovery 09/6/2016 12:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes, NMOCD Trishia, BLM	
By Whom? Joseph McLaughlin	Date and Hour: 09/6/2016 08:15 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Describe Area Affected and Cleanup Action Taken.*

A 240 BBL Produced Water release occurred on the ConocoPhillips Buck Federal CTB located in Lea County, New Mexico: MSO was making his rounds when he noticed water inside the berm located around the oil and water tanks. When inspecting it more closely, the water was coming from a broken water line located on the filtration line near the filters. MSO shut down the water filtration pumps and closed the line that comes from tanks to the pump. MSO called to notify supervisor and had a water truck vacuum out the produced water from the berm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Joseph McLaughlin		OIL CONSERVATION DIVISION	
Signature:		Approved by Environmental Specialist: <i>Jamie Keyes</i>	
Printed Name: Joseph McLaughlin			
Title: HSE	Approval Date: 09/07/2016	Expiration Date: 11/07/2016	
E-mail Address: Joe.P.McLaughlin@conocophillips.com	Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.		Attached <input type="checkbox"/> IRP 4431
Date: 09/6/2016	Phone: 806-567-2790		

* Attach Additional Sheets If Necessary

nJXK1625144979
pJXK1625145108