

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 1:01 pm, Sep 07, 2016

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

Accepted as initial only.

### OPERATOR

☒ Initial Report ☒ Final Report



Name of Company: Chevron USA Inc.	Contact: Josepha DeLeon	
Address: 6301 Deauville, Midland, TX 79706	Telephone No.: 575-263-0424	
Facility Name: R.E. Cole NCT No. 004	Facility Type: Central Tank Battery	
Surface Owner	Mineral Owner	API No. 30-025-10316

### LOCATION OF RELEASE

Unit Letter A	Section 16	Township 22s	Range 37e	Feet from the 554	North/South Line North	Feet from the 554	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release: Spill in secondary, lined containment	Volume of Release: 7.36 barrels fluid (6.85 BW and .51 BO)	Volume Recovered: 7.36 barrels fluid (6.85 BW and .51 BO)
Source of Release: Tank over fill	Date and Hour of Occurrence: 8/24/2016: 2:00 pm	Date and Hour of Discovery: 8/24/2016: 2:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes	
By Whom? Josepha DeLeon	Date and Hour: 8/24/2016; 2:30 pm via voicemail	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*  N/A		
Describe Cause of Problem and Remedial Action Taken.*  Tank run over due to RICE operating's disposal line back flowing on our lease. Pump lost power in the storm and the check valves were bad due to corrosion which contributed to this as well. Shut in and called vac truck was called to pick up the spill.		
Describe Area Affected and Cleanup Action Taken.  All in secondary, lined containment. Recovered all the fluid, there is gravel/dirt on top of the plastic liner and will be cleaned with microbial product (Gator).		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Josepha DeLeon	Approved by Environmental Specialist: 	
Title: HES Compliance Support - Environmental	Approval Date: 09/07/2016	Expiration Date: 11/07/2016
E-mail Address: jdx@chevron.com	Conditions of Approval: pending inspection	Attached <input type="checkbox"/> IRP 4433
Date: August 31, 2016	Phone: 575-263-0424	

\* Attach Additional Sheets If Necessary

nJXK1625146605  
pJXK1625146678