

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 7:25 am, Sep 08, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	KING TUT FEDERAL #002H	Facility Type:	Tank Battery
Surface Owner:	Federal	Mineral Owner:	API No. 30-025-41558

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	30	24S	32E	190'	North	1650'	West	Lea

Latitude 32.1950645 Longitude 103.717659

NATURE OF RELEASE

Type of Release:	Oil & Produced Water	Volume of Release:	23bbls of Oil & 34bbls of Produced Water	Volume Recovered:	22bbls of Oil & 33bbls of Produced Water
Source of Release:	Valve	Date and Hour of Occurrence:	9/5/2016 12:00 am	Date and Hour of Discovery:	9/5/2016 12:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mr. Amos - BLM / Ms. Lynch - SLO		
By Whom?	Robert Grubbs Jr.	Date and Hour:	Tue 9/6/2016 9:42 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a valve being opened on a recirculating pump. Place the valve in the correct position.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the BLM and the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist: 	
Title:	Senior Environmental Coordinator	Approval Date:	09/08/2016
E-mail Address:	rgrubbs@concho.com	Expiration Date:	11/08/2016
Date:	September 7, 2016	Phone:	432-683-7443
		Conditions of Approval:	Attached <input type="checkbox"/> 1RP 4434
		Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/ approval.	

* Attach Additional Sheets If Necessary

nJXK1625226595
pJXK1625226673