

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	East Eumont Battery	Facility Type	Battery

Surface Owner	State	Mineral Owner		API No.	30-025-05545
---------------	-------	---------------	--	---------	--------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	3	19S	37E					Lea County, NM

Latitude N 32.68473° Longitude W 103.24536°

### NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	50 bbls oil, 10 bbls produced water	Volume Recovered	60 bbls
Source of Release	Lack of communication caused a tank to spill	Date and Hour of Occurrence	09/01/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jamie Keyes, Kristen Lynch-NMOCD		
By Whom?	Kathy@ BBC International, Inc.	Date and Hour	09/02/2016 @ 11:01 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**REVIEWED**

**By Kristen Lynch at 9:40 am, Sep 19, 2016**



Describe Cause of Problem and Remedial Action Taken.\*

Lack of communication caused a tank to spill over 50 bbls of oil and 10 bbls of produced water. A vacuum truck recovered all free-standing fluids and communication was re-established.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 85' x 65' on location inside the berm. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:					
Printed Name:	Casey Summers	Approved by Environmental Specialist: 			
Title:	NM Environmental Advisor	Approval Date:	09/19/2016	Expiration Date:	11/19/2016
E-mail Address:	Casey_Summers@oxy.com	Conditions of Approval:	Discrete Samples Only Please submit a remediation plan by 10/19/2016.		
Date:	9-14-16	Phone:	(575) 513-8289	Attached	<input type="checkbox"/> 1RP 4443

\* Attach Additional Sheets If Necessary

nKL1626333807  
pKL1626334330