

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

REVIEWED

By Kristen Lynch at 9:39 am, Sep 27, 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Prize 27 Federal #2 CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-31902

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	27	22S	32E					Lea County, NM

Latitude N 32.35699° Longitude W 103.65582°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	60 bbls	Volume Recovered	59 bbls
Source of Release	Valve on circulating line left open	Date and Hour of Occurrence	09/08/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jamie Keyes, Kristen Lynch-NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis	Date and Hour	05/09/2016 @ 10:08am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The valve on the circulating line was left open causing 60 bbls of oil to spill inside the containment. A vacuum truck recovered 59 bbls and the valve was restored to the correct position.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 40' x 120' on location inside containment. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain releases with the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Casey Summers		Approved by Environmental Specialist: 	
Title: NM Environmental Advisor		Approval Date: 9/27/2016	Expiration Date: 11/27/2016
E-mail Address: Casey.Summers@oxy.com		NMOCD Accepts Discrete Samples only Conditions of Approval: Please Notify NMOCD Prior to Sampling	
Date: 9-20-16	Phone: (575) 513-8289	Attached <input type="checkbox"/> IRP 4451	

* Attach Additional Sheets If Necessary

Please submit Remediation Plan no later than
10/27/2016.

nKL1627133614
pKL1627134598