

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

REVIEWED

By Kristen Lynch at 11:00 am, Sep 27, 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	PO Box 4294; Houston, TX 77210	Telephone No.	(575) 513-8289
Facility Name	WBR Federal #2 CTB	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API No.	30-025-32999
---------------	-----	---------------	--	---------	--------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	13	22S	32E					Lea County, NM

Latitude N 32.38570° Longitude W 103.63564°

### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	80 bbls	Volume Recovered	77 bbls
Source of Release	Compromised 2" steel water line	Date and Hour of Occurrence	09/13/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kristen Lynch-NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis	Date and Hour	09/13/2016 @ 4:43 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A compromised 2" steel water line caused 80 bbls of produced water to leak on location. A vacuum truck recovered 77 bbls of oil and the line was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 50' x 50' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Casey Summers		Approved by Environmental Specialist: 	
Title: NM Environmental Advisor		Approval Date: 9/27/2016	Expiration Date: 11/27/2016
E-mail Address: Casey.Summers@oxy.com		NMOCD Accepts Discrete Samples Only	
Date: 9-20-16 Phone: (575) 513-8289		Conditions of Approval: Notify NMOCD prior to Sampling Please submit a Remediation Plan no later than 10/27/2016	
		Attached <input type="checkbox"/> IRP 4453	

\* Attach Additional Sheets If Necessary

nKL1627139171  
pKL1627139369