District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

State of New Mexico **Energy Minerals and Natural Resources**

Form C-141

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1RP 4460

nKL1627239908 pKL1627240237

Release Notification and Corrective Action										
							OPERATOR Initial Report Final Report			
						Contact Danny Velo, Production Foreman				
						Telephone No. 575-703-3360				
Facility Name Hulkster 3						Facility Type Oil				
Surface Owner State Mineral Owner						State			API No 30-025-39570	
LOCATION OF RELEASE										
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/West Line County		
В	32	18S	32E	660	FNL 1980			FEL Lea		
Latitude: 32.7094536 Longitude: -103.7863235										
NATURE OF RELEASE										
Type of Release						Volume of Release Volume Recovered				
Oil and Produced Water						101bbls oil water	and 10bbls produ	uced 101bbls	101bbls oil and 10bbls produced water	
Source of Release						Date and Hour of Occurrence			Date and Hour of Discovery	
Circulating line Was Immediate Notice Given?						September 13, 2016 @ 9:30 AM September 13, 2016 @ 9:30 AM If YES, To Whom? September 13, 2016 @ 9:30 AM				
Was Immediate Notice Given?						Jamie Keyes, OCD				
By Whom?						Date and Hour September 13, 2016 @ 2:50 PM				
Danny Velo, Production Foreman Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse				
☐ Yes ⊠ No						N/A				
If a Watercourse was Impacted, Describe Fully.* N/A										
Describe Cause of Problem and Remedial Action Taken. * Circulating line developed a hole causing a release into lined containment. The circulating line was shut and oil was moved to a different tank in case of hole in current tank. Repairs are scheduled to be made.										
Describe Area Affected and Cleanup Action Taken.* Approximately 101bbls oil and 10bbls produced water was released from the circulating line into the surrounding lined containment. All released fluid remained in lined containment. A vacuum truck was called and recovered 101blls oil and 10bbls produced water from containment. The containment was checked for holes and none were found. No further action is required.										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.										
Signature: Sheila Fisher						OIL CONSERVATION DIVISION				
						Approved by Environmental Specialist				
Printed Name: Sheila Fisher						Approved by Environmental Specialist:				
Title: Field Admin Support						Approval Dat	e: 9/28/2016	Expiration	Date: N/A	
E-mail Address: Sheila.fisher@dvn.com						Conditions of	Approval: N/A	X	Attached	

Date: 9/14/16

* Attach Additional Sheets If Necessary

Phone: 575.748.1829

REVIEWED By Kristen Lynch at 11:03 am, Sep 28, 2016

District I 1625 N. French Dr., Hobbs, NM 88240 1220 S. St. Francis Dr., Santa Fe, NM 87505







