

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

REVIEWED

By Kristen Lynch at 10:10 am, Oct 20, 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: BRANEX COG FEDERAL #010	Facility Type: Battery	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-40871

LOCATION OF RELEASE

Unit Letter L	Section 9	Township 17S	Range 32E	Feet from the 1650	North/South Line South	Feet from the 330	East/West Line West	County Lea
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

32.846405,-103.7790375

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 25 bbls PW	Volume Recovered: 20 bbls PW
Source of Release: Flow line	Date and Hour of Occurrence: 9/24/2016 @ 7:00 PM	Date and Hour of Discovery: 9/24/2016 @ 7:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kristen Lynch/NMOCD & Shelly Tucker/BLM	
By Whom? Dakota Neel	Date and Hour: 9/26/2016	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release occurred when a truck pulling a trailer hit the produced water line. The damaged portion of the water line was replaced.

Describe Area Affected and Cleanup Action Taken.*

This release occurred and remained on the lease road. Vacuum trucks were immediately dispatched to recover standing fluids. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel	Approved by Environmental Specialist: 	
Title: Environmental Coordinator	Approval Date: 10/19/2016	Expiration Date: 12/18/2016
E-mail Address: dneel2@concho.com	NMOCD accepts discrete samples only.	
Date: October 5, 2016 Phone: 575-748-6933	Conditions of Approval: Notify NMOCD prior to sampling. Please submit remediation plan no later than 11/19/2016	Attached <input type="checkbox"/> 1RP 4468

* Attach Additional Sheets If Necessary

nKL1629436032
pKL1629436449