

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

REVIEWED

By Kristen Lynch at 10:58 am, Oct 20, 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: <b>ConocoPhillips</b>	Contact: <b>Jose A Zepeda</b>	
Address: <b>1410 N West County Rd</b>	Telephone No. <b>575-391-3165</b>	
Facility Name: <b>SEMU Strawn #167</b>	Facility Type: <b>Flowline</b>	
Surface Owner: Federal	Mineral Owner: N/A	API No. <b>30-025-035938</b>

### LOCATION OF RELEASE

Unit Letter	Section 25	Township 20S	Range 37E	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Lea</b>
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release: <b>Oil</b>	Volume of Release: <b>6.8</b>	Volume Recovered: <b>6.0</b>
Source of Release: <b>Flowline</b>	Date and Hour of Occurrence <b>10/06/16 0830</b>	Date and Hour of Discovery <b>SAME</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kristen Lynch, Shelly Tucker	
By Whom? <b>Jose A Zepeda</b>	Date and Hour: <b>10/07/16 0715 Via Email</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*  N/A		

Describe Cause of Problem and Remedial Action Taken. \*

On October 6, 2016 at 0830 hrs. at SEMU Strawn #167 a leak was found on a flowline resulting in a release of 6.8 bbls of oil with 6.0 bbls recovered. Immediate action was to shut in well and turn in work order for repairs. Spill site will be remediated according to COPC and NMOCD guidelines.

Describe Area Affected and Cleanup Action Taken. \*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>JOSE A ZEPEDA</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jose A Zepeda		Approved by Environmental Specialist: <i>Kristen Lynch</i>	
Title: LEAD HSE		Approval Date: <b>10/20/2016</b>	Expiration Date: <b>12/20/2016</b>
E-mail Address: <b>Jose. A. Zepeda@conocophillips.com</b>		Attached <input type="checkbox"/>	
Date: 10/07/2016 Phone: 575-391-3165		NMOCD accepts discrete samples only Conditions of Approval: Notify NMOCD prior to all sampling Please submit remediation plan no later than 11/20/2016.  1RP 4469	

\* Attach Additional Sheets If Necessary

nKL1629437630  
pKL1629439321