

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

REVIEWED

By Kristen Lynch at 10:39 am, Sep 28, 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Patterson B-52 Federal Com #002H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-40773
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 5	Township 19S	Range 32E	Feet from the 330	North/South Line North	Feet from the 330	East/West Line East	County Lea
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

32.6958351,-103.7809525

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 240 bbls Oil	Volume Recovered: 237 bbls Oil
Source of Release: Tank Overflow	Date and Hour of Occurrence: 9/19/2016 @ 12:00 PM	Date and Hour of Discovery: 9/19/2016 @ 2:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kristen Lynch/NMOCD & Shelly Tucker/BLM	
By Whom? Dakota Neel	Date and Hour: September 20, 2016 @ 3:15 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release occurred when a circulating pump malfunctioned and overfilled the storage tank. The circulating pump has been replaced.

Describe Area Affected and Cleanup Action Taken.*

This release was contained within a lined facility. Vacuum trucks were immediately dispatched to recover all standing fluids. The contaminated gravel will be replaced with fresh gravel and the facility will be pressure washed and cleaned.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel	Approved by Environmental Specialist: 	
Title: Environmental Coordinator	Approval Date: 9/28/2016	Expiration Date: 11/28/2016
E-mail Address: dneel2@concho.com	NMOCD Accepts Discrete Samples Only Conditions of Approval: Please submit a Remediation plan no later than 10/28/2016. Notify OCD prior to all sampling	
Date: September 26, 2016	Phone: 575-748-6933	Attached <input type="checkbox"/> IRP 4459

* Attach Additional Sheets If Necessary

nKL1627238045
pKL1627238244