

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Music Master 27 Federal #003H	Facility Type: Battery	
Surface Owner: Federal	Mineral Owner:	API No. 30-025-43387

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	27	25S	35E	330	North	2250	East	Lea

Latitude 32.1076877 Longitude -103.3541299

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 104 bbls PW	Volume Recovered: 102 bbls PW
Source of Release: Filter Pot/Battery	Date and Hour of Occurrence: April 29, 2017 2:00 am	Date and Hour of Discovery: April 29, 2017 2:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu/NMOCD, Shelly Tucker/BLM	
By Whom? Dakota Neel	Date and Hour: 4/29/2017 9:40 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 12:57 pm, May 03, 2017



Describe Cause of Problem and Remedial Action Taken.*

This release occurred when a 1/2" nipple blew out of the top of filter pot located within the battery. The nipple and associated ball valve have been replaced.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility and a light mist impacted the adjacent pasture. Vacuum trucks were immediately dispatched to recover all free standing fluids within the lined containment. Concho will have the spill area in the pasture sampled to delineate any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel	Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 5/3/2017	Expiration Date:
E-mail Address: dneel2@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: April 29, 2017 Phone: 575-746-2010	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

NMOCD requests confirmation
samples in the impacted
pasture as indicated above.

1RP-4688

nOY1712347134

pOY1712347368