

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Co LP (6137)	Contact Stephen Richards, Devon Completions Foreman
Address PO BOX 250, Artesia, NM 88211	Telephone No. (575) 252-3717
Facility Name: Transfer line from Ursula Frac Pond to North Thistle 2 State 2H	Facility Type Oil well

Surface Owner: See Page 2 Location of Release	Mineral Owner: See Page 2 Location of Release	API No. 30-025-42821
-----------------------------------------------	-----------------------------------------------	----------------------

LOCATION OF RELEASE: Please see Page 2 for locations of the spills related to this incident.

Unit Letter	Section	Township 23S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea	
-------------	---------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------	--

Latitude See Page 2 Location of Release Longitude See Page 2 Location of Release

NATURE OF RELEASE


Type of Release: Treated Produced Water	Volume of Release: 355 bbls total (pad and pasture)	Volume Recovered: 250 bbls (on pad)
Source of Release: Lay Flat Hose	Date and Hour of Occurrence: 10/23/2017, 6:00 & 7:30 PM	Date and Hour of Discovery 10/23/2017, 6:00 & 7:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD: Olivia Yu BLM: Shelly Tucker	RECEIVED By Olivia Yu at 7:48 am, Nov 17, 2017
By Whom? Mike Shoemaker, EHS Professional	Date and Hour: OCD: 10/25/17, 7:24 AM BLM: 10/25/17, 7:24 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	

If a Watercourse was Impacted, Describe Fully.* NA

Describe Cause of Problem and Remedial Action Taken.*
At 6:00 PM, the lay flat hose transferring treated produced water from the Ursula frac pond to location failed at Site #1 (see attached GIS map). The frac went from flush and then shut down, releasing produced water to the ground. Repairs were made to the hose and completion activities resumed. At 7:30 PM, there were four additional failures along the line. Completion activities shut down. The line is being replaced.

Describe Area Affected and Cleanup Action Taken.* There were a total of five different spill sites from the pond to the pad location along the lay flat line, which are identified on the attached GIS map with their respective chronologic number. The estimated square footage affected by each release is as follows: 1) 5,600' 2) 7,744' 3) 400' 4) 1,974' 5) 115,480'. An estimated 355 barrels total of treated produced water were spilled and 250 barrels were recovered from the combined locations. A remediation contractor will be contacted to assist with the delineation and remediation efforts.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Denise Menoud	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Approved by Environmental Specialist: 	
Title: Admin Field Support	Approval Date: 11/17/2017	Expiration Date:
E-mail Address: denise.menoud@dmn.com	Conditions of Approval: see attached directive	Attached <input checked="" type="checkbox"/>
Date: 10/25/2017 Phone: (575)746-5544		

* Attach Additional Sheets If Necessary

1RP-4868

nOY1732130408

pOY1732130912

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

- PAGE 2

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Co LP (6137)	Contact Stephen Richards, Devon Completions Foreman
Address PO BOX 250, Artesia, NM 88211	Telephone No. (575) 252-3717
Facility Name: Transfer line from Ursula Frac Pond to North Thistle 2 State 2H	Facility Type Oil well

Surface Owner: State / Federal	Mineral Owner: State / Federal	API No. 30-025-42821
--------------------------------	--------------------------------	----------------------

LOCATION OF RELEASES:

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
		23S	33E					Lea

SITE 1) M-02-23S-33E, 32.326430 N, 103.549980 W (Surface Owner-State, Mineral Owner-Federal)	11-D
SITE 2) L-11-23S-33E, 32.316493 N, 103.551181 W (Surface Owner-State, Mineral Owner-Federal)	
SITE 3) E-11-23S-33E, 32.321643 N, 103.550924 W (Surface Owner-State, Mineral Owner-Federal)	
SITE 4) F-02-23S-33E, 32.336293 N, 103.546804 W (Surface Owner-State, Mineral Owner-State)	
SITE 5) B-02-23S-33E, 32.339810 N, 103.540839 W (Surface Owner-State, Mineral Owner-State)	

Signature: Denise Menoud		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Denise Menoud		Approved by Environmental Specialist:	
Title: Admin Field Support	Approval Date:	Expiration Date:	
E-mail Address: denise.menoud@dvn.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 10/25/2017	Phone: (575)746-5544		

* Attach Additional Sheets If Necessary

Total Spilled 350 BPW

N Thistle 2 St 2H

5

Lat: 32.339810° N
Lon: 103.540839° W

4

Lat: 32.336293° N
Lon: 103.546804° W

Site 5

Site 4

1

Lat: 32.326430° N
Lon: 103.549980° W

Site 1

3

Lat: 32.321643° N
Lon: 103.550924° W

Site 3

2

Lat: 32.316493° N
Lon: 103.551181° W

Site 2

Ursula

N Thistle 2 St 2H Spill 10/23/2017



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Menoud
Map is current as of: 25-Oct-2017



Miles

0 0.14 0.28 0.56 1:28,457

■ Devon Maintained City
Boundaries
□ Devon Maintained City
ETJ

Operator/Responsible Party,

The OCD has received the form C-141 you provided on _11/6/2017_ regarding an unauthorized release. The information contained on that form has been entered into our incident database and remediation case number _1RP-4868_ has been assigned. **Please refer to this case number in all future correspondence.**

It is the Division's obligation under both the Oil & Gas Act and Water Quality Act to provide for the protection of public health and the environment. Our regulations (19.15.29.11 NMAC) state the following,

The responsible person shall complete division-approved corrective action for releases that endanger public health or the environment. The responsible person shall address releases in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with 19.15.30 NMAC. [emphasis added]

Release characterization is the first phase of corrective action unless the release is ongoing or is of limited volume and all impacts can be immediately addressed. Proper and cost-effective remediation typically cannot occur without adequate characterization of the impacts of any release. Furthermore, the Division has the ability to impose reasonable conditions upon the efforts it oversees. **As such, the Division is requiring a workplan for the characterization of impacts associated with this release be submitted to the OCD District _1_ office in __Hobbs__ on or before _12/17/2017_. If and when the release characterization workplan is approved, there will be an associated deadline for submittal of the resultant investigation report. Modest extensions of time to these deadlines may be granted, but only with acceptable justification.**

The goals of a characterization effort are: 1) determination of the lateral and vertical extents along with the magnitude of soil contamination. 2) determine if groundwater or surface waters have been impacted. 3) If groundwater or surface waters have been impacted, what are the extents and magnitude of that impact. 4) The characterization of any other adverse impacts that may have occurred (examples: impacts on vegetation, impacts on wildlife, air quality, loss of use of property, etc.). To meet these goals as quickly as possible, the following items must, at a minimum, be addressed in the release characterization workplan and subsequent reporting:

- Horizontal delineation of soil impacts in each of the four cardinal compass directions. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. This is not an exclusive list of potential contaminants. Analyzed parameters should be modified based on the nature of the released substance(s). Soil sampling must be both within the impacted area and beyond.
- Vertical delineation of soil impacts. Adsorbed soil contamination must be characterized for the following constituents using the associated laboratory methods: benzene, toluene, ethylbenzene, and total xylenes by either Method 8260 or 8021, total petroleum hydrocarbons by Method 8015 extended range (GRO+DRO+MRO; C₆ thru C₃₆), and for chloride by Method 300. As above, this is not an exclusive list of potential contaminants and can be modified. Vertical characterization samples should be taken at depth intervals no greater than five feet apart. Lithologic description of encountered soils must also be provided. At least ten vertical feet of soils with contaminant concentrations at or below these values must be demonstrated as existing above the water table.
- Nominal detection limits for field and laboratory analyses must be provided.
- Composite sampling is not generally allowed.
- Field screening and assessment techniques are acceptable (headspace, titration, EC [include algorithm for validation purposes], EM, etc.), but the sampling and assay procedures must be clearly defined. Copies of field notes are highly desirable. A statistically significant set of split samples must be submitted for confirmatory laboratory analysis, including the laterally farthest and vertically deepest sets of soil samples. Make sure there are at least two soil samples submitted

for laboratory analysis from each borehole or test pit (highest observed contamination and deepest depth investigated). Copies of the actual laboratory results must be provided including chain of custody documentation.

- Probable depth to shallowest protectable groundwater and lateral distance to nearest surface water. If there is an estimate of groundwater depth, the information used to arrive at that estimate must be provided. If there is a reasonable assumption that the depth to protectable water is 50 feet or less, the responsible party should anticipate the need for at least one groundwater monitoring well to be installed in the area of likely maximum contamination.

- If groundwater contamination is encountered, an additional investigation workplan may be required to determine the extents of that contamination. Groundwater and/or surface water samples, if any, must be analyzed by a competent laboratory for volatile organic hydrocarbons (typically Method 8260 full list), total dissolved solids, pH, major anions and cations including chloride and sulfate, dissolved iron, and dissolved manganese. The investigation workplan must provide the groundwater sampling method(s) and sample handling protocols. To the fullest extent possible, aqueous analyses must be undertaken using nominal method detection limits. As with the soil analyses, copies of the actual laboratory results must be provided including chain of custody documentation.

- Accurately scaled and well-drafted site maps must be provided providing the location of borings, test pits, monitoring wells, potentially impacted areas, and significant surface features including roads and site infrastructure that might limit either the release characterization or remedial efforts. Field sketches may be included in subsequent reporting, but should not be considered stand-alone documentation of the site's layout. Digital photographic documentation of the location and fieldwork is recommended, especially if unusual circumstances are encountered.

Nothing herein should be interpreted to preclude emergency response actions or to imply immediate remediation by removal cannot proceed as warranted. Nonetheless, characterization of impacts and confirmation of the effectiveness of remedial efforts must still be provided to the OCD before any release incident will be closed.

Jim Griswold

OCD Environmental Bureau Chief
1220 South St. Francis Drive
Santa Fe, New Mexico 87505
505-476-3465
jim.griswold@state.nm.us