

From: [Yu, Olivia, EMNRD](#)
To: [Frank Engallina](#)
Cc: [Jason Wacker](#)
Subject: RE: Angell #1 Tank Battery Closure Report (IRP #1849)
Date: Tuesday, October 31, 2017 3:09:00 PM
Attachments: image001.png
image002.png
approved_Closure Report - Angell #1 Tank Battery (IRP# 1849) Remediation 09112017.pdf
approved_1RP #1849 Angell #1 Final C-141 10202017.pdf

Mr. Engallina:

The available information indicates **OPERATOR** has met the requirements of 19.15.29 NMAC and no further corrective action is required. NMOCD considers **1RP-1849** closed. This determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

Please see attachments for your records.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Frank Engallina [mailto:pikeenergyservices@gmail.com]
Sent: Monday, October 23, 2017 9:38 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Cc: Jason Wacker <jwacker@bcoperating.com>
Subject: Re: Angell #1 Tank Battery Closure Report (IRP #1849)

Olivia,

Thank you for the reminder. Attached is a copy of the final C-141. Please let me know if any edits are required on the form.

Best Regards,

Frank Engallina

Pike Energy Services, LLC

321 Pike Road

San Antonio, TX 78209

210.363.2431 cell

pikeenergyservices@gmail.com



From: "Yu, Olivia, EMNRD" <Olivia.Yu@state.nm.us>

Date: Thursday, October 19, 2017 at 10:06 AM

To: Frank Engallina <pikeenergyservices@gmail.com>

Cc: Jason Wacker <jwacker@bcoperating.com>

Subject: RE: Angell #1 Tank Batter Closure Report (IRP #1849)

Mr. Engallina:

A final C-141 is still required to close IRP-1849.

Thanks,
Olivia

From: Yu, Olivia, EMNRD

Sent: Monday, October 2, 2017 2:23 PM

To: 'Frank Engallina' <pikeenergyservices@gmail.com>

Cc: Jason Wacker <jwacker@bcoperating.com>

Subject: RE: Angell #1 Tank Batter Closure Report (IRP #1849)

Mr. Engallina:

NMOCD accepts the closure report and grants closure to IRP-1849. Please see the attachment for your records.

Please submit a final C-141 form to complete the closure:

<http://www.emnrd.state.nm.us/OCD/forms.html>

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Frank Engallina [<mailto:pikeenergyservices@gmail.com>]
Sent: Monday, September 11, 2017 12:56 PM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Cc: Jason Wacker <jwacker@bcoperating.com>
Subject: Angell #1 Tank Batter Closure Report (IRP #1849)

Ms. Yu,

I am pleased to submit this closure report for your review. The site has been backfilled and graded.

Please call me if you have any questions or comments.

Thank you,

Frank Engallina

Pike Energy Services, LLC
321 Pike Road
San Antonio, TX 78209
210.363.2431 cell
pikeenergyservices@gmail.com

