

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

| | | | |
|-----------------|--------------------------------|---------------|---------------|
| Name of Company | OXY USA WTP LP | Contact | WADE DITTRICH |
| Address | PO BOX 4294; HOUSTON, TX 77210 | Telephone No. | 575-390-2828 |
| Facility Name | North Hobbs GSAU Unit 0534-33 | Facility Type | Satellite |
| Surface Owner | State | Mineral Owner | STATE |
| | | API No. | 30-025-34373 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| K | 33 | 18S | 38E | | | | | LEA |

Latitude 32.7031 _ Longitude -103.152 _ NAD83

NATURE OF RELEASE

| | | | | | |
|--|---|---|-----------------|----------------------------|----------|
| Type of Release | Produced Water | Volume of Release | 100 bbls | Volume Recovered | 0 bbls |
| Source of Release | Zap Lock Inj. Line | Date and Hour of Occurrence | 6-26-18 | Date and Hour of Discovery | 12-19-17 |
| Was Immediate Notice Given? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | OLIVIA YU-NMOCD | | |
| By Whom? | WADE DITTRICH | Date and Hour | 6-26-18 | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |
| If a Watercourse was Impacted, Describe Fully.* | | | | | |
| <div>RECEIVED By Olivia Yu at 8:59 am, Jul 19, 2018</div> | | | | | |

Describe Cause of Problem and Remedial Action Taken.*



3 inch Zaplock pipe separated causing a spill of 100 bbls of produced water onto location. No fluids were recovered and inj. line was repaired and put back into service

Describe Area Affected and Cleanup Action Taken.*

LEAK GPS: 32.702996 -103.154437

The affected area is 40ft x 90ft on location (measurements are subject to change with GPS tracking). Remediation will be completed in accordance with a remediation plan approved by the NMOCD and the SLO.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--|---|------------------|-----------------------------------|
| Signature:  | OIL CONSERVATION DIVISION | | |
| Printed Name: WADE DITTRICH | Approved by Environmental Specialist:  | | |
| Title: ENVIROMENTAL SPECIALIST | Approval Date: | Expiration Date: | |
| E-mail Address: wade_dittrich@oxy.com | Conditions of Approval: | | Attached <input type="checkbox"/> |
| Date: 7/17/2018 | Phone: 575-390-2828 | | |

* Attach Additional Sheets If Necessary

1RP-5121

From: [Yu, Olivia, EMNRD](#)
To: [Dittrich, John W](#); [Mann, Ryan](#)
Cc: [Hernandez, Christina, EMNRD](#)
Subject: RE: North Hobbs GSAU Unit 0534-33
Date: Thursday, July 19, 2018 9:32:00 AM
Attachments: updated_1RP5121_Corrected Signed-Initial C141.pdf

Good morning Mr. Dittrich:

Thank you for the revised initial C-141 with the updated GPS coordinates for the release location. The same 1RP-5121 is used. Please note that the release occurred on State surface and minerals ownership. All communications and report submittals must be send to all corresponding agencies.

Also, NMOCD visited the release location (NHGSAU 0534-33 well pad) as indicated on the first initial C-141 on Tuesday, July 17, 2018. Please be advised that any standing fluids and impacted surface soil should be removed as soon as possible, in addition to any surficial placement of pea gravel or similar absorbent.

Thanks,
Olivia

From: Dittrich, John W <Wade_Dittrich@oxy.com>
Sent: Wednesday, July 18, 2018 9:15 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Subject: North Hobbs GSAU Unit 0534-33

Olivia,

Here is the corrected **Initial C141**. Sorry for the incorrect information. Thank you.

Wade Dittrich
Environmental Specialist
Oxy Permian-New Mexico
575-390-2828 cell
575-397-8214 office
Wade_Dittrich@Oxy.com