

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC (OGRID #229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Osprey 20 State Com #003H	Facility Type: Tank Battery	
Surface Owner: State	Mineral Owner: State	API No. 30-025-40969

LOCATION OF RELEASE

Unit Letter K	Section 20	Township 21S	Range 34E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.463732 Longitude -103.494739 NAD83

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 5 bbl.	Volume Recovered: 1 bbl.
Source of Release: Valve Failure	Date and Hour of Occurrence: August 10, 2018 9:36am	Date and Hour of Discovery: August 10, 2018 9:36am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 10:51 am, Aug 20, 2018



Describe Cause of Problem and Remedial Action Taken.*

Packing in the oil dump caused it to fail allowing the tanks to overflow and spray out of the flare.

Describe Area Affected and Cleanup Action Taken.*

The release was within a pasture. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area sampled to delineate any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: DeAnn Grant		Approved by Environmental Specialist: 	
Title: HSE Administrative Assistant	Approval Date: 8/20/2018	Expiration Date:	
E-mail Address: agrant@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: August 13, 2018	Phone: 432-253-4513		

* Attach Additional Sheets If Necessary

nOY1823239315

pOY1823239504

See NMAC 19.15.29 for
conditions. Please be advised
that release characterization must
be completed before any
significant remedial activities.

1RP-5158