

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Marathon Oil Company	Contact Callie Karrigan
Address 5555 San Felipe Street, Houston, Texas 77056	Telephone No. 405-202-1028(cell) 575-297-0956 (office)
Facility Name Chili Parlor 17 Fed 2H	Facility Type Oil well

Surface Owner: state	Mineral Owner: federal	API No. 30-025-43137
----------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	8	22S	33E	240	South	360	East	Lea

Latitude 32.39971673 Longitude -103.58819381 NAD83

NATURE OF RELEASE

Type of Release: oil	Volume of Release 8.50 gallons	Volume Recovered 0 gallons
Source of Release: flare	Date and Hour of Occurrence 05/06/2018 1:07 pm	Date and Hour of Discovery 05/06/2018 1:07 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Lea County – Olivia Yu, BLM – Shelly Tucker	
By Whom? Callie Karrigan	Date and Hour 05/06/2018 5:50 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
Not applicable.

APPROVED

By Olivia Yu at 7:32 am, Sep 19, 2018


Describe Cause of Problem and Remedial Action Taken.*

Operator reported that the oil dump on the heater treater failed closed, sending fluid down the flare line and out the flare. Approximately 8.50 gallons of oil was released out the flare in light mist and overspray.

Describe Area Affected and Cleanup Action Taken.*

The overspray affected a 108 ft x 252 ft area, with the mist traveling west off location into a pasture. A surficial scrape (0-6 inches) was performed to recover lightly saturated soil. Confirmation samples were taken and outlined in the report prepared by Vertex.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Callie Karrigan</i>	OIL CONSERVATION DIVISION	
Printed Name: Callie Karrigan	Approved by Environmental Specialist: 	
Title: HES Professional	Approval Date: 9/19/2018	Expiration Date: xx/xx/xxxx
E-mail Address: cnkarrigan@marathonoil.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/18/2018 Phone: 405-202-1028 (cell) 575-297-0956 (office)	BLM & NMSLO approval	

* Attach Additional Sheets If Necessary

1RP-5072

