

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Marathon Oil Company	Contact: Jennifer Van Curen	
Address: 5555 San Felipe St., Houston, TX 77056	Telephone No.: 713-296-2500	
Facility Name: Warren State #1	Facility Type: Oil Well	
Surface Owner:	Mineral Owner: State	API No.: 30-025-34034

LOCATION OF RELEASE

Unit Letter P	Section 35	Township 15S	Range 37E	Feet from the 1295	North/South Line FSL	Feet from the 880	East/West Line FEL	County Lea
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	---------------

Latitude 32.9701576 Longitude -103.1650467 NAD83

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 6.7 bbls	Volume Recovered: 5 bbls
Source of Release: Oil Tank	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 10/04/2017: 1500 hrs
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Jason Wardell	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 10:06 am, Oct 06, 2017


Describe Cause of Problem and Remedial Action Taken.*

As a result of a small hole in an inactive tank on the Warren State #1, approximately 6.7 bbls of oil spilled into the secondary containment. All fluid has been removed from damaged tank.

Describe Area Affected and Cleanup Action Taken.*

The area affected was a 26' X 34' area. Vacuum truck was called out to pick up standing fluid, material in containment will be removed as well.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jason Wardell</i>		OIL CONSERVATION DIVISION	
Printed Name: Jason Wardell		Approved by Environmental Specialist: 	
Title: HES Professional		Approval Date: 10/6/2017	Expiration Date:
E-mail Address: jlwardell@marathonoil.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/05/2017 Phone: 307-272-1632		Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

Release #3

nOY1727947865