

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Production LLC (OGRID#217955)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443	
Facility Name: Bebidas State #002H	Facility Type: Tank Battery	
Surface Owner: State	Mineral Owner: State	API No.: 30-025-40855

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	16	23S	33E	392	South	1887	West	Lea

Latitude: 32.2985573 Longitude: -103.5797043 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 7bbls	Volume Recovered: 5bbls
Source of Release: Filter pot fitting	Date and Hour of Occurrence: 1/12/2018	Date and Hour of Discovery: 1/12/2018 12:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 11:04 am, May 07, 2018

Describe Cause of Problem and Remedial Action Taken.*

The nipple on the bottom of the filter pot failed due to corrosion resulting in the release. The nipple was replaced with a stainless steel nipple.

Describe Area Affected and Cleanup Action Taken.*

All of the fluid remained inside of the lined containment. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

of

Signature:

Dakota Neel

Printed Name: Dakota Neel

Title: HSE Coordinator

Approval Date: **5/7/2018**

Expiration Date: **xx/xx/xxxx**

E-mail Address: dneel2@concho.com

Conditions of Approval:

Attached ☐

Date: 1/24/2018

Phone: 575-746-2010

* Attach Additional Sheets If Necessary

nOY1801736002

From: [Yu, Olivia, EMNRD](#)
To: [Dakota Neel](#); [Mann, Ryan](#)
Cc: [Rebecca Haskell](#); [Robert McNeill](#); [Sheldon Hitchcock](#); [Christopher Gray](#)
Subject: RE: (C-141 Final) Bebidas State #2H (30-025-40855) 1-12-2018
Date: Monday, May 7, 2018 11:08:00 AM
Attachments: approved_(C-141 Final) Bebidas State #2H (30-025-40855) 1-12-2018.pdf
image003.png

Dear Mr. Neel:

The available information indicates **OPERATOR** has met the requirements of 19.15.29 NMAC and no further corrective action is required. NMOCD considers **nOY1801736002** closed. This determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Dakota Neel <DNeel2@concho.com>
Sent: Wednesday, January 24, 2018 4:55 PM
To: Mark Naranjo <mnanranjo@slo.state.nm.us>; Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Honea, Tammy <thonea@slo.state.nm.us>
Cc: Billings, Bradford, EMNRD <Bradford.Billings@state.nm.us>; Rebecca Haskell <RHaskell@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Christopher Gray <CGray@concho.com>
Subject: (C-141 Final) Bebidas State #2H (30-025-40855) 1-12-2018

Ms. Yu/Mr. Naranjo,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and

found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thanks,

Dakota Neel
HSE Coordinator
COG Operating LLC
Cell: [432-215-2783](tel:432-215-2783)
dneel2@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.