Form 3160-5 (April 2004)	SUNDRY	UNITED STATES DEPARTMENT OF THE BUREAU OF LAND MAN NOTICES AND REF	INTERIOR AGEMENT PORTS ON			324 LC 063200		
	Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals EIVED					6. If Indian, Allottee or Tribe Name NA		
S	SUBMIT IN TRIPLICATE- Other instructions on reverse side.					or CA/Agreement, Name a	nd/or No.	
1. Type of Well Oil Well: Gas Well: Other					AN 8. Well Na	ume and No.		
2. Name of Operator Mesquite SWD, Inc.						a Federal SWD #2		
3a Address	79, Carlsbad, NM 8		3b. Phone No. (ir 575-706-1840	,		i-40813 Ind Pool, or Exploratory Ai	/ 	
		T., R., M., or Survey Description)	/		SWD;	Bell Canyon & Cherry		id j
500' FSL &	2,000' FEL Sec. 2	2, T25S-R32E		11. County or Parish, State Lea Co., NM				
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, I								
TYPE OF SUBMISSION TYPE OF ACTION								
Notice o	f Intent	Deepen Fracture Treat	eat Reclamation (Start/Resume) Water Shut-Off					
Subsequ	andonment Notice	Casing Repair Change Plans	Plug and Aban					
testing ha determine Spud 1 10/24/2 1.75 cf 10/26/2 (@ 4,77 2nd tai 11/3/20 11/4/20 11/6/20 12/7/20 12/10/2	as been completed. Fin ed that the site is ready 0/23/2012 w/20" bin 2012 Drilled 12-1/4i 7/sx 13.5# 160 sx, ta 2012 Notified Lea C 2012 Notified Lea C 20 w/ DV tool @2,12 1 C w/100 sx 1.33 cf 212 Reached 6,628' s 212 Released rig. Se 212 Cleaned location 212 Ran Photo Dens	t set 20' 16" conductor cmtd w # hole to 919'. Notified Lea Co il 200 sx 1.34 cf/sx 14.8#, circ o BLM Office of BOP test by o BLM Office at 4,790' prep t 1'. Cmt 35/65 POZ/C 1st stag /sx 14.8#. Circ cmt on both sta and having difficulty maintair t well head. Removed Closed 1 n and ready for inspection. ity and Compensated Neutron 748.45' 4-1/2" 11.6# Salta line	filed only after all re //150 cf cmt, circ f BLM Office to ri 118 sx to pit. WO Man Services. Ter o run 7" csg. Noti e 260 sx 2.04 cf/sx ages. WOC 24 hr: hing satisfactory c Loop equipment. h. Found TD @6,4	equirements, including reclam to surface. WOC. un csg. Ran 882'- 9-5/8" J C st OK, DO shoe w/ 8-3/4" fied BLM Office running t 12.6# and 200 sx 1.33 cf/ s. irculation. Elected to tem	ation, have bee -55 36# STC bit. csg, prep to sx 14.8#, 2nd porarily leav	en completed, and the ope ', cmt w/lead Class "C' cement. Ran 7" 23# L l stage 260 sx 2.04 cf/sz ve open hole @6,628'.	rator has ' 160 sx -80 LTC set x 12.6# and	L
14. Thereby	certify that the fore Printed/Typed)	going is true and correct				JWL		, イ
Kay Havenor				Title Geologist 575-626-4518				
Signature	Kory H	branor	Da		2/17/2012 ACC		RECOR	ז
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant helds legal or equitable title to those rights in the subject leas which would entitle the applicant function in the subject leas Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any p States any false, fictitious or fraudulent statements or representations as to any matter of				Office		/s/ Chris W	013 alls HAGEMENT	
	is on page 2)   ( ( M f T	DIL CONSERVATION Completions on Injection AIT test & Chart witness ull set of logs, Deviation to be sent to the OCD H before injection starts.	DIVISION req n or SWD we sed, Completi	uires for Federal lls. on Form 3160-3,	:		FEB 0	<b>5</b> 2013

....

۰.

## Order of the Authorized Officer

## Mesquite SWD, Inc. Paduca - 02 API 3002540813, T25S-R32E, Sec 22 January 29, 2013

Compliance with the APD ¶ VII. DRILLING A: #4. and ¶ F. Production Test is required. Submit sundry subsequent report documentation to support these requirements. Also submit the required completion report.

## Well with a Packer - Operations

- 1) Conduct a Mechanical Integrity Test of the tubing/casing annulus after a tubing, packer or casing seal is established. Repair that seal any time more than five barrels of packer fluid is replaced within 30 days.
- 2) The minimum test pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with a minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need to be reduced). An alternate method for a BLM approved MIT is to have the fluid filled system open to atmospheric pressure and have a loss of less than five barrels in 30 days witnessed by a BLM authorized officer.
- 3) Document the pressure test on a one hour full rotation calibrated recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict injection approval. In Lea County email Andy Cortez <u>acortez@blm.gov</u>, (phone 575-393-3612 or 575-631-5801). If no answer, leave a voice mail or email with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 4) Submit a subsequent Sundry Form 3160-5 relating the MIT activity. Include a copy of the recorded MIT pressure chart. List the name of the BLM witness, or the notified person and date of notification. NMOCD is to retain the original recorded MIT chart.
- 5) Use of tubing internal protection, tubing on/off equipment just above the packer, a profile nipple, and an in line tubing check valve below the packer or between the on/off tool and packer is a "Best Management Practice". The setting depths and descriptions of each are to be included in the subsequent sundry. List (by date) descriptions of daily activity of any previously unreported wellbore workover.
- 6) Submit the original subsequent sundry with three copies to BLM Carlsbad.
- 7) Compliance with a NMOCD Administrative Order is required, submit documentation of that authorization. Approved injection pressure compliance is required. If injection pressure

exceeds the approved pressure you are required to reduce that pressure and notify the BLM within 24 hours.

- 8) When injection pressure is within 50 psig of the maximum pressure, install automation equipment that will prevent exceeding that maximum. Submit a subsequent report (Sundry Form 3160-5) describing the installed automation equipment within 30 days.
- 9) Unexplained significant variations of rate or pressure to be reported within 5 days of notice.
- 10) The casing/tubing annulus is required to be monitored for communication with injection fluid or loss of casing integrity. A BLM inspector may request verification of a full annular fluid level at any time.
- 11) A "Best Management Practice" is to maintain the annulus full of packer fluid at atmospheric pressure. Equipment that will display on site, continuous open to the air fluid level is necessary to achieve this goal.
- 12) Loss of packer fluid above five barrels per month indicates a developing problem. Notify BLM Carlsbad Field Office, Petroleum Engineering within 5 days.
- 13) A suggested format for monthly records documenting that the casing annulus is fluid filled is available from the BLM Carlsbad Field Office.
- 14) Gain of annular fluid requires notification within 24 hours. Cease injection and maintain a production casing pressure of 0psia. Notify the BLM's authorized officer ("Paul R. Swartz" <<u>pswartz@blm.gov</u>>, cell phone 575-200-7902). If there is no response phone 575-361-2822.
- 15) Submit a (Sundry Form 3160-5) subsequent report (daily reports) describing all wellbore activity and Mechanical Integrity Test as per item 1) above. Include the date(s) of the well work, and the setting depths of installed equipment: internally corrosive protected tubing, tubing on/off equipment just above the packer, and an in line tubing check valve below the packer or between the on/off tool and packer. The setting depths and descriptions of each are to be included in the subsequent sundry. List daily descriptions of any previously unreported wellbore workover(s) and reason(s) the well annular fluid was replaced.

## Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil and gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.