Submit 3 Copies Te Appropriate District	Otata of Nam Marina		Form C-103
Office Carlos Energy	State of New Mexico	WELL API NO.	October 25, 2005
1625 N. French Dr., Hobbs, NM 88240 HOBBS OCD	Minerals and Natural Resources		r 40704
District II	ONSERVATION DIVISION		5-10761 <i>(</i>
1301 W. Grand Ave., Artesia, NW 88210	CHSERVATION DIVISION	5. Indicate Type of Leas	se
	220 South St. Francis Dr.	STATE	✓ FEE □
District IV	Santa Fe, NM 87505	6. State Oil & Gas Leas	se No.
1220 S. St. Francis Dr., Santa Fe, NM RECEIVED		BO-01	158-0019
87505 SUNDRY NOTICES AND REPO	OTS ON WELLS	7. Lease Name or Unit	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO			
A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		New Mexico BZ State NCT-8	
PROPOSALS.)	<i>C</i> .	8. Well Number	
1. Type of Well: Oil Well Gas Well Other	1-14		3
2. Name of Operator		9. OGRID Number	0070
Apache Corporati 3. Address of Operator	on	10. Pool Name	0873
303 Veterans Airpark Lane, Ste. 3000, Midland, TX, 79705		Langlie Mattix;7Rvrs-Q-Grayburg	
4. Well Location			
Unit Letter J : 1980	feet from the S line and	1980 feet from the	e E line
Section 16 Township	23S Range 37E	NMPM	County Lea
11. Elevation (S	how whether DR, RKB,RT, GR, etc.) 3304' GR		
3304 GR			
12. Check Appropriate Box To Indicate Nature of N	otice, Report, or Other Data		
NOTICE OF INTENTION TO		SUBSEQUENT RE	_
PERFORM REMEDIAL WORK PLUG AND ABAN		☐ ALTERING	CASING []
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMP	COMMENCE DRILLING OF CASING/CEMENT JOB	PNS. PANDA	Y
DOWNHOLE COMMINGLE	L CASING/CEIVIENT JOB		
OTHER:		eady for OCD inspection	after P&A
✓ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. ✓ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
ODERATOR MARKE LEASE MARKE WELL MURAPER ARIAMINAPER QUARTER/QUARTER/OCATION OR			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MA		43 DEEN WELDED OK	
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from the lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.) ✓ All other environmental concrens have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accorda		ids have been removed fro	m
non-retrieved flow lines and pipelines.	````		
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.			
Inspection has to be made to a PAA location because it of	oes not meet the chiena above, a penalty h	lay be assessed.	
SIGNATUREZ en SILVIA	TITLE P&A Technic	an DATE	3/6/13
2			0.0.10
TYPE OR PRINT NAME Leon Sellers	E-MAIL <u>leon.sellers@apache</u>	corp.com PHONE:	432-208-0349
For State Use Only			
APPROVED BY: Washer hitaken	TITLE Compliance O	Hicar DATE	03-12-2013
Conditions of Approval (if any):	THE STATE OF THE PROPERTY OF T	I II O I DATE	08122015