

Submit 1 Copy To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico
Energy, Minerals and Natural Resources
APR 03 2013
RECEIVED
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
October 13, 2009

WELL API NO. 30-025-33521
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> Fed
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name DIAMONDTAIL 24 FEDERAL
8. Well Number 1
9. OGRID Number 6137
10. Pool name or Wildcat SWD; DIAMONDTAIL BONE SPRING

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other SWD

2. Name of Operator
DEVON ENERGY PRODUCTION CO. LP

3. Address of Operator
PO BOX 250, ARTESIA, NM 88211

4. Well Location

Unit Letter: E; 1980 feet from the NORTH line and 330 feet from the WEST line

Section 24 Township 23S Range 32E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3731' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please review attached, Bradenhead Test Report with chart.

The well was tested at 350 PSI and held for 45 minutes. All visible lines had 0 PSI and no leaks. Test was completed on 03/21/2013.

Spud Date:

Rig Release Date:

DENIED
START PSI 560 #
FIN 360

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Gracie Bustamante

TITLE Field Admin Support

DATE: 04/02/2013

Type or print name: Gracie Bustamante

E-mail address: Gracie.Bustamante@dmn.com

PHONE: 575-746-5561

For State Use Only

APPROVED BY:

[Signature]

TITLE

Dist. MGR


DATE

4-8-2013

Conditions of Approval (if any):

APR 08 2013

h



h