

APR 29 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-24645
Property Name North Vacuum-ABC North Unit	Well No. #002

2. Surface Location

UL - Lot H	Section I	Township 17S	Range 34E	Feet from 1980	N/S Line North	Feet From 860	E/W Line East	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status A	SHUT-IN	PRODUCING INT ^A	DATE 04-17-2013
------------------	---------	-------------------------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	05			50	3950
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N (Fresh)	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	X	FRESH	SALTY	X	SULFUR	BLACK
-------	---	-------	-------	---	--------	-------

Remarks:

Surface had about 1 gal H2O (brine) down to 0. Prod csg had about 5 gals H2O (fresh with KCL) & Pkr fluid down to 0.

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

Signature: <i>Trish Mealand</i>	ECG/ODD 4-29-2013
Printed name: Trish Mealand	OIL CONSERVATION DIVISION
Title: Production Analyst	Entered into RBDMS
E-mail Address: pmealand@limerockresources.com	Re-test
Date: 04-23-2013	
Phone: 575-623-8424	
Witness:	

MAY 06 2013

h