

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6181 Fax: (575) 393-0720

APR 29 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Lime Rock Resources II-A, L.P.	API Number 30-025-24648
Property Name North Vacuum ABO North Unit	Well No. #162

7. Surface Location

UL - Lot L	Section 36	Township 16S	Range 34E	Feet from 1780	N/S Line South	Feet From 460	E/W Line West	County Lea
---------------	---------------	-----------------	--------------	-------------------	-------------------	------------------	------------------	---------------

Well Status

Well Status	SHUT-IN TA	PRODUCING E	DATE 04-17-2013
-------------	---------------	----------------	--------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0	n/a	n/a	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	X	FRESH	SALTY	X	SULFUR	BLACK
-------	---	-------	-------	---	--------	-------

Remarks:

Well TA'd. Surface had about 5 gals of H2O to 0. Very salty & clear.

Tested by Eddie Elliott 432-413-0429

Reported by Trish Mealand 575-623-8424

Signature <i>Trish Mealand</i>	OIL CONSERVATION DIVISION
Printed name: Trish Mealand	Entered into RBDMS
Title: Production Analyst	Re-test
E-mail Address: pmcaland@limerockresources.com	
Date: 04-23-2013	Phone: 575-623-8424
Witness:	

ELG/ocd 4-29-2013

MAY 06 2013