HOBBS OCD

District 1 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax (575) 393-0720

> State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

APR 29 20.3

RECEIVED

BRADENHEAD TEST REPORT Operator Name Lime Rock Resources II-A, L.P ²⁴ API Number 30-025-29382 Property Name North Vacuum ABO North Unit Well No. #002 1 ⁷. Surface Location E/W Line Feet from N/S Line UL - Lot Section Township Range Feet From County 660 М 2 17S 34E South 660 West Lea Well Status SHUT-IN PRODUCING DATE Well Status Б 04-17-2013 ΤA OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH **OBSERVED DATA** If bradenhead flowed water, check all of the descriptions that apply: (E)Tubing (A)Surf-Interm (B)Interm(1)-Interm(2) (C)Interm-Prod (D)Prod Csng Puff Q Ø Pressure Q Flow Characteristics Puff Y/N Y7 N Y/N Y/N Y/ N Steady Flow Y/N YIN Y/ N Y/N Y7 N Surges Y7 N Y/N Down to nothing Y/N Y/N Y/N Y / NGas or Oil Y/N Y7 N Y/N Y/N Water Y7 N Y/N Y/N Y7 N If bradenhead flowed water, check all of the descriptions that apply: FRESH CLEAR SALTY SULFUR BLACK Remarks: Tested by Eddie Elliott 432-413-0429 Reported by Trish Mealand 575-623-8424 CD 4-29-2013 ElG Signature: OIL CONSERVATION DIVISION Printed name: Trish Mealand Entered into RBDMS Title: Production Analyst Re-test E-mail Address: pmealand/@limerockrespurces.com Date: 04-23-2013 Phone: 575-623-8424 Witness:

ſ