Submit 1 Copy To Appropriate District	State of New Mexic)	Form C-103
Office <u>District I</u> - (575) 393-6161	- (575) 393-6161 Energy, Minerals and Natural Resources		Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API	NO. 30-005-00827
811 S. First St., Artesia, NM 88210			Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		TE X FEE
<u>District IV</u> (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 8750	6. State Oil	& Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS			ame or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM <u>C-101)</u> FOR SUCH			Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Quer Injection		8. Well Nu	mber 16
			Number
Celero Energy II, LP			247128
3. Address of Operator ₄₀₀ W. Illinois, Ste. 1601 Midland, TX 79701			nme or Wildcat
4. Well Location	. 17101	Caprock; Qu	leen
	980 feet from the N	line and 1980	eet from the W
Section 23 Township 13S Range 31E NMPM County Chaves			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
DESCRIPTION RESIDENCE OF THE PROPERTY OF THE P			RECORD STATE OF THE PROPERTY O
12. Check A	ppropriate Box to Indicate Natu	re of Notice, Report or C	Other Data
NOTICE OF INT	TENTION TO:	SUBSECUENT	T REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	DMMENCE DRILLING OPNS	S. PANDA
PULL OR ALTER CASING	MULTIPLE COMPL CA	ASING/CEMENT JOB	
DOWNHOLE COMMINGLE			<i>(</i>
OTHER:	□ o.	THER: Unsuccessful attempt	to return to injection X
	eted operations. (Clearly state all perti		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
4/4/13 - MIRU. Found 2 3/8" x 4' tbg sub in WH. No tbg in well. Replace tbg head with 2000#, 4 1/2" x 2 3/8" Larkin WH. MI 106			
jts of 2 3/8" tbg WS. Tally same. PU and run tbg WS, 4 1/2" csg scraper & 3 3/4" bit. Ran to 2980'. Rotate string with torque. Did not indicate to be rotating on metal. TOH w/ tbg & BHA. Attempt to run A & M's 4 1/2" RBP. Unable to get into top of 4 1/2" csg to run			
& set at 2975'. Ran & rotate 3 7/8" tapered mill into top of 4 1/2" csg. Able to get mill through tight spot. Attempt to re-run RBP into 4 1/2" csg. Still would not go. Stopping at the gauge rings on RBP.			
4/5/13 - Replace 4 1/2" RBP. TIH w/ tbg WS & 4 1/2" Cline RBP. Ran & set at 2975'. Attempt to load hole with PW. Failed to fill up. TOH w/ tbg & retreiving head for RBP. Ran 40 arm caliper magnetic log (CIL) from 300' to 2956'. Ran GR/CBL from 1650' to			
2956'. TIH w/ pkr. Tested 4 1/2" csg at 490', 60' & 5'; csg leaking out surface pipe at all of the above footages (leak in surface pipe			
was just below the surface pipe well head). Ran tbg with pkr to 1030' & tested down tbg. Pressure to 500# and leaked off 200# to 300# in 1 min. Tested 3 times with same results. Lower pkr to RBP, latched onto same and TOH, LD tbg WS with tools.			
300# in 1 lilli. Tested 3 times with	same results. Lower pkr to KBF, rater	ed onto same and Torr, ED	tog wa with tools.
G : 132 :	D: D1 D		
Spud Date:	Rig Release Date:		·
I hereby certify that the information a	bove is true and complete to the best of	of my knowledge and belief.	
,		,	
SIGNATURE LIA Y	Yant TITLE Regulatory	Analyst	DATE <u>04/09/2013</u>
			DUONE: (422)(06, 1002
Type or print name Lisa Hunt For State Use Only	PHONE: <u>(432)686-1883</u>		
	/ //	l no	577
APPROVED BY	TITLE US7	NOZ	DATE
Conditions of Approval (it any):)		
	•		DATE 5-7-2013 Chm
			· · · ·