, OCD			
Submit One Copy To Oppropriate District	State of New Mexic	co	Form C-103
District I	Energy, Minerals and Natural	Resources	Revised Nøvember 3, 2011 WELL API NO.
1625 N. French Dr., Hobba NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 CENED <u>District III</u>	OIL CONSERVATION D	IVISION	30-025-40083
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Honey 13 /	
1. Type of Well: Oil Well Gas Well Other		8. Well Number 1	
2. Name of Operator / Nearburg Producing Company		9. OGRID Number 15742	
3. Address of Operator		10. Pool name or Wildcat	
3300 N. A Street, Bldg. 2, Midland, TX 79705 4. Well Location			Humble City; Strawn South
Unit Letter B: 280 feet from the N line and 2450 feet from the E line			
Section 13 Township 17S Range 37E NMPM County Lea			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3724' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK AL			LING OPNS. ☐ P AND A 🗵
OTHER:		☐ Location is rea	ady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.) All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
Gray Surface Specialties, Agent SIGNATURE Uch Gray Surface Specialties, Agent TITLE for Nearburg Producing Company DATE 5/21/2013			
TYPE OR PRINT NAME Vicki Johns For State Use Only	ton E-MAIL: V	/johnston1@gm	PHONE:(830) 537-4599
APPROVED BY: Maley Stown Pittle Compliance Officer Date 6/5/2013			
, 0		ı	JUN 0 5 2013