Submit One Copy To Appropriate District Office State of New Mexic	co Form C-103
Office District 1 1625 N. French Dr., Hobbs, NM 882440BBS District II	Resources Revised November 3, 2011 WELL API NO.
District II 811 S. First St., Artesia, NM 88210 District III District III District III 1220 South St. Franci	IVISION 30-025-10685
District III 1220 South St. Franci	5. Indicate Type of Lease s Dr. STATE STEE
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 8750	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	301940
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR S	7. Lease Name or Unit Agreement Name Skelly Penrose B Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 42,
2. Name of Operator	9. OGRID Number
Providence Energy Services, Inc. dba Kelton Operating 3. Address of Operator	10. Pool name or Wildcat
P.O. Box 928, Andrews, TX 79714-0928	Langlie Mattix (37240)
4. Well Location	
Unit Letter D: 660 feet from the North line and 660 feet from the West line	
Section 9 Township 23-S Range 37-E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	EMEDIAL WORK ALTERING CASING
	OMMENCE DRILLING OPNS. P AND A SING/CEMENT JOB
	<u></u>
OTHER:	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	·
When all work has been completed, return this form to the appropriate Dist	rict office to schedule an inspection.
SIGNATURE TITLE President DATE 09/25/2012	
TYPE OR PRINT NAME <u>C. Dale Kelton</u> E-MAIL: <u>pro</u> <u>For State Use Only</u>	ovidenceenergy@suddenlink.net PHONE: 432-661-1364
Released	
APPROVED BY: Wall White TITLE LONG Viduce Officer DATE 10/10/2012	
Conditions of Approval (if any):	released PEB 0 3 2014 Povidence energy@suddenlink.net PHONE: 432-661-1364 Released DATE 10/10/2012