Submit 3 Copies To Appropriate District State of New Me	
Office Energy, Minerals and Natural Resources October 25, 2007 District I 1635 N French Dr. Hobbs NM 87246 OPDC OCD WELL API NO.	
1625 N. French Dr., Hobbs, NM 872400BBS OCD District II	
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 01L CONSERVATION 1220 South St. Fra	DIVISION 5 Latiente Time of Land
1000 Rio Brazos Rd., Aztec, NM 87719 B 1 3 2014 Santa Fe, NM 87	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 27820
SUNDRY NOR CON WEL	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10 PROPOSALS.)	R PLUG BACK TO A West Towington Strawn Unit
	8. Well Number
1. Type of Well: 🚾 Oil Well 🗌 Gas Well 🗌 Other	18
2. Name of Operator	9. OGRID Number
Energen Resources Corporation           3. Address of Operator	162928 / 10. Pool name or Wildcat
3300 N. "A" St., Bldg 4, Ste. 100, Midland, TX 79705	Lovington, Strawn, West
4. Well Location	
Unit Letter <u>D</u> : 655 feet from the <u>North</u> line and <u>330</u> feet from the <u>West</u> line	
Section 5 Township 168 Range 36E NMPM County Less, New Mercico	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3945' CL	
12. Check Appropriate Box to Indicate Nature of Notice,	
NOTICE OF INTENTION TO:           PERFORM REMEDIAL WORK []	
	COMMENCE DRILLING OPNS.
OTHER:	Location is ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
<b>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</b>	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. AU INFORMATION HAS BEEN WELDED OR BEDMANENTLY STAMPED ON THE MADVED'S SUDFACE	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other-production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
	bases have been removed. (Poured onsite concrete bases do not have
to be removed.)	
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from	
non-retrieved flow lines and pipelines. Electricity on Location Runs TANK Battery.	
LIECTVICITY ON L	SCATION RUNS I AND DAMERY.
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
SIGNATURE TITL	E DATE 2/13/14
Rest Smith	rex.gmith@energen.com
TYPE OR PRINT NAME $\_$ E-MA	AIL PHONE PHONE
For State Use Only Mala Difference and Council and Cou	
APPROVED BY THELE AT A TOWN TITLE COMPLIANCE ATTE AT 4 2014	
Conditions of Approval, if any	
	FEB 18 2014 \

yr

NA