HOBBS OCD

State of New Mexico

MAR 28 2014 Energy, Minerals and Natural Resources Department

Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

				22422							
Operator Name RICE OPERATING COMPANY 30-								-025-371			
Property Name BLINEBRY DRINKARD								•	'ell No. 120 -		
					7. Sur	face Location					
UL - Lot D	Section 20	Township 22S	Range . 37E			Feet from 330	N/S Line N		Feet From 660	E/W Line W	County LEA
					W	ell Status					
Well Status		;	ACTIVE SHUT-IN		PRODUCING INJECTION SWD			3-12-14			
	OPE	N BRADENI	HEAD AND IN	TERMEDIA	TE TO	ATMOSPHERE	INDIVIDU	IALLY F	OR 15 MINU	TES EACH	-

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf	(B)Interm(1)	(C)Interm-	(D)Prod Csng	(E)Tubing
Pressure					-/7
Flow Characteristics	0	0			
Puff ·	Y / (Ñ)	(Q)/ N	Y / N	(Ý) N	CO2
Steady Flow	Y / 🐠	Y / AD	Y/N	Y / (N)	GAS
Surges	Y / (N)	Y / (N)	Y / N	Y / 🕦	Type of Fluid
Down to nothing	Y / 🚱	Y / (N)	Y / N	Y / 🔕	Injected for
Gas or Oil	¥ 7 🔊	Y / 🗞	Y / N	Y / (N)	Waterflood if applies.
Water	Y / (N)	Y / (N)	Y / N	¥ 7 🔊	appaes

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
L			I	L.,

Remarks: Note - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Accepted for Record Only

OIL CONSERVATION DIVISION

Entered into RBDMS

Re-test

E-mail Address:

Date: 7. ./4

Title: Far 1

Phone: < 5.1.2 . @95[△]

Witness: 1/n