в

5

HOBBS OCD

JUL 1 0 2014

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

API Number

LEA

EAST

2317

OCCIDENTAL PERMIAN, LTD								30-025-07614	
Property Name SOUTH HOBBS (G/SA) UNIT								W	ell No. 14 L
^{7.} Surface Location									
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County

NORTH

334

Well Status

Well Status	SHUT-IN	PRODUCING	DATE	
W Ch Status		V	1-26-14	

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

19-S

38-E

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	Q	50	1	115	/20
Flow Characteristics					
Puff		Y/N	₩ N N	N N	
Steady Flow	V7N	(V)-N	Y Q	Y/N	
Surges		Y/N	\mathbf{Y}/\mathbf{N}		
Down to nothing	<u>U</u> N	C/ N	Ų N ∩	N N	
Gas or Oil	Y/(N	Y/N	Y/N	Y N	
Water	Y/N/	Y/Ŋ	Y / N	Y/W]

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
Remarks:	I		INJECTING AT THIS TIME	
Mal o	Land			ECORD ONLY 7/11/2014
Signature: The				// 11/ 2014
<u>Γ</u> Υ		m		INSERVATION DIVISION
Printed name: MEN	DY JOHNSON	·····	Entered into I	RBDMS
Title: ADMINISTR	ATIVE ASSOCIATE		Re-test	

E-mail Address: mendy_johnson@oxy.com Date: 782014 Pho

 O
 I
 Phone: 806-592-6280

 Witness:
 Witness:

JUL

4 2014

1