

State of New Mexico  
 Energy, Minerals and Natural Resources Department  
 Oil Conservation Division Hobbs District Office

SEP 16 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name <b>CHEURON</b>	API Number <b>30-025-33052</b>
Property Name <b>WARN STATE A/C 1</b>	Well No. <b>001</b>

Surface Location									
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
<b>K</b>	<b>31</b>	<b>17S</b>	<b>35E</b>		<b>2036</b>	<b>FSL</b>	<b>2260</b>	<b>FWL</b>	<b>LEA</b>

Well Status									
TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE	
YES	NO	YES	NO	INJ	SWD	<u>OIL</u>	GAS		
								<b>7/28/14</b>	


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<b>0</b>	<b>0</b>		<b>40</b>	<b>280</b>
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

**FOR RECORD ONLY**

**B8 9/19/2014**

Signature: 	OIL CONSERVATION DIVISION
Printed name: <b>Dane McQueen</b>	Entered into RBDMS
Title: <b>Production Specialist</b>	Re-test
E-mail Address: <b>lomb@chevron.com</b>	
Date: <b>8/15/14</b>	Phone: <b>575-942-3526</b>
Witness:	

SEP 22 2014