
THE TOP THE PROPERTY OF THE PR

In Reply Refer to 3162.4 (P0220)

United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene Carlsbad, New Mexico 88220-6292 www.nm.blm.gov



JAN 15 2015

RMR Operating, LLC 415 W. Wall Street, Suite 1700 Midland, TX 79701

30-025-40340

Gentlemen:

Your Application for Permit to Drill (APD) for the well listed below has expired because drilling has not commenced per Onshore Order #1:

LEASE

WELL NAME AND LOCATION

EXPIRATION

NM93223

Madera 19 Federal 3H

November 12, 2013

330' FNL & 2260' FWL, sec. 19, T. 26 S., R. 35 E.

If the well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM so we may correct our records.

If you wish to drill this well at a later date, please submit a complete application (1 original and 3 copies) to this office. Since the original APD has expired, the resubmitted APD will be subject to all processing requirements including the \$6,500 application fee and the 30-day posting period. Please note on the resubmitted APD that it was previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions, please contact Jim Amos at (575) 234-5909.

Sincerely,

Stephen J. Caffey

Assistant Field Manager, Lands & Minerals

aph I Copy

cc: NMOCD

FEB 0 6 2015