

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 14 2015

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Apache Corp.		API Number 30-025-06353	
Property Name NEDU		Well No. 319	

7. Surface Location

UL - Lot 0	Section 2	Township 21S	Range 37E	Feet from 1650	N/S Line S	Feet From 990	E/W Line E	County Lea
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ SWD	PRODUCER OIL ☐ GAS ☐	DATE 3-27-15
--	--	--	---	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	$\emptyset$	$\emptyset$	N/A	$\emptyset$	1050
Flow Characteristics					
Pull	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	CO2 ☐
Steady Flow	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	WTR ☒
Surges	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	GAS ☐
Down to nothing	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	Type of Fluid
Gas or Oil	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	Injected for
Water	Y/ ☒ N	Y/ ☒ N	Y/N	Y/ ☒ N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/28/2015

Signature: Tracy Cole		OIL CONSERVATION DIVISION	
Printed name: Tracy Cole		Entered into RBDMS	
Title: Pumper		Re-test	
E-mail Address: tracy.cole@apachecorp.com			
Date: 3-27-15	Phone: 575-441-5196		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM

AUG 04 2015