

JUL 30 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name XTO Energy, Inc	API Number 30-025-28924
Property Name Seven Rivers Queen Waterflood, North	Well No. 11

7. Surface Location

UL - Lot G	Section 4	Township 22S	Range 36E	Feet from 2623	N/S Line North	Feet From 2636	E/W Line East	County Lea
---------------	--------------	-----------------	--------------	-------------------	-------------------	-------------------	------------------	---------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	PRODUCER OIL	GAS	DATE 3-25-2015
------------------	----	----------------	----	-----	-----------------	-----------------	-----	-------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	Ø	Ø		Ø	400
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR —
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Alan Miller</i>	Oil Conservation Division
Printed name: ALAN MILLER	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 3-25-2015	Phone: 575-441-1641
Witness:	

AUG 12 2015